

## UNIT-I

### MEASURING INSTRUMENTS

#### Introduction:-

The measurement of a given quantity to the result of comparison between the quantity to be measured and a definite standard. The instruments which are used for such measurement are called measuring instruments. The three basic quantities in the electrical measurements are current, voltage and power.

→ The instrument which measures the current flowing in the circuit is called Ammeter.

→ The instrument which measures the voltage across any two points of a circuit is called Voltmeter.

→ The instruments which are used to measure the power are called power meters or wattmeter.

The action of almost all the analog ammeter and voltmeter depends on the deflecting torque produced by an electric current. In ammeters such a torque is proportional to the current measured. In voltmeter torque is decided by a current which is proportional to the voltage to be measured. Thus all the analog ammeters and voltmeters are basically current measuring devices.

The necessary requirements for any measuring instruments are:

- With the introduction of the instrument in the circuit, the circuit condition should not be altered. Thus the quantity to

be measured should not get affected due to the instrument used.

③ The power consumed by the instruments for their operation should be as small as possible.

→ measuring instruments are classified as:-

- Absolute instruments
- Secondary instruments.

Classification of measuring instruments :-

① Indicating Instruments:-

Thus instruments make use of a dial and points are showing or indicating magnitude of unknown quantity. The Examples are ammeters, voltmeter etc. and also spectrometer.

② Recording Instruments:-

These instruments give a continuous record of the given electrical quantity which is being measured over a specific period. Examples are various types of recorders. In such recording instruments. The readings are recorded by drawing the graph Ex:- ECG, Seismic graphs measured and records details of Earth quakes as far as for and duration.

③ Integrating Instruments:-

These instruments measure the total quantity of electricity delivered over a period of time.

Ex:- Household Energy meter.

Essential Requirements of an instrument:-

In case of measuring instruments the effect of the quantity is converted into another

-transmitted to the pointer which moves over a calibrated scale. For satisfactory operation of any indicating instruments following system must be present in a instrument.

1. Deflecting System producing deflecting torque  $T_d$ .

2. Controlling System producing Controlling torque  $T_c$ .

3. Damping System producing damping torque  $T_d$ .

Absolute :-

Gives the magnitude and the quantity measured in terms of the deflection obtained during the measurement.

Ex:- Tangent galvanometer.

Secondary :- It does not need any calibration.

Ex:- Ammeter, voltmeter, wattmeter.

Deflecting System :- In most of the indicating instruments the mechanical force proportional to the quantity to be measured is generated.

This force or torque deflects the pointer. The system which produces such a deflecting torque is called deflecting system and the torque is denoted as  $T_d$  the deflecting torque overcomes.

(1) The inertia of the moving system.

(2) The Controlling torque provided by Controlling System.

(3) The damping torque provided by of damping system.

The deflecting system uses one of the following Effects produced by current or voltage, to produce deflecting tor-

(1) magnetic Effect :-

When a current carrying conductor is placed in uniform magnetic field, it experiences a force which causes to move it. This effect is mostly used in many instrument

like moving iron attraction & repulsion type, permanent magnet moving coil instruments etc.

### ② Thermal Effect:

The current to be measured is passed through a small element which heats it to cause rise in temperature which is converted to an Emf by a thermo couple attached to it. When two dissimilar metals are connected End to End to form a closed loop and the two junctions formed are maintained at different temperatures then E.m.f is induced which causes the flow of current through the closed circuit which is called a thermo couple.

### ③ Electrostatic Effects:

When two plates are charged, there is a force exerted b/w them, which moves one of the plates. This effect is used in Electrostatic instruments which are normally voltmeters.

### ④ Induction Effect:

When a non magnetic conducting disc is placed in a magnetic field produced by electro magnetic which are excited by alternating currents an Emf is induced in it.

If a closed path is provided there is a flow of current in the disc. The interaction b/w induced current of the alternating magnetic fields, exerts a force on the disc. which causes it to move. This interaction is called an induction effect. This principle is mainly used in Energy meters.

### ⑤ Hall Effect:

If a bar of semi conducting material is placed in uniform magnetic field and if the bar carries current, then an

magnetic field, current passing through the conducting bar and hall effect coefficient, which is constant for a given semiconductor. This effect is mainly used in flux

imeters. of galvanic or d'Arsonval type with controlling system. It is probably up to 200 H.P.


This system should provide a force so that current or any other electrical quantity will produce deflection of the pointer proportional to its magnitude. The important parts of this system are.

- ① It produces a force equal and opposite to the deflecting force in order to make the deflection of pointer at a definite magnitude. If this system is absent, then the pointer will swing beyond its final steady position for the given magnitude and deflection will become infinite.
- ② It brings the moving system back to zero position when the force which causes the movements of the moving system is removed. It force which causes the coil never come back to its zero position in the absence of controlling system.

### Gravity control :-

→ This type of control consists of a pointer

small weight attached to this consuming system where position is a controllable.



- of the weight in the fig &.
- If the system deflects, the co-weight position also changes as shown in figure 8.
- The system deflects through an angle  $\theta$  is the cont. weight acts at a discharge its from the centre.
- The component as  $\sin\theta$  of this weight tries to restore the pointer back to the zero position. This is the restoring force displacement, but the controlling torque  $T_c$ .

Thus controlling torque

$$T_c = w \sin \theta / s$$

$$K \sin \theta$$

similar to where  $k = ws$  = gravity control constant

Now generally all meters are current sensing meters

where, Deflecting torque

$$T_d = k_f I$$

as  $k_f$  is another constant

In equilibrium position,  $T_d = T_c$

$$k_f I = K \sin \theta$$

$$I \propto \sin \theta$$

∴ Thus the deflection is proportional to Current i.e. quantity to be measured.

Note:-

But as it is a function of  $\sin \theta$ , the scale for the instrument using gravity control is not uniform.

Advantages:-

1. Its performance is not time dependent.
2. It is simple and cheap.
3. The controlling torque can be varied by adjusting the position of the control co-weight.
4. Its performance is not temperature dependent.

- The scale is non uniform causing problems to reduce errors in readings.
- The system must be used in vertical position only and must be properly levelled. Otherwise it may cause serious errors in the measurements.

### Spring Controls

→ Two hair springs are attached to the moving system which exerts controlling torque. To empty Spring Control to an instrument, following requirements are essential.

- The spring should be non-magnetic.
- The spring should be free from mechanical stress.
- The spring should have a small resistance, sufficient cross-sectional area.
- It should have low resistance temperature coefficient.

The arrangement of the springs is shown in the fig.


→ The springs are made up of non-magnetic materials like silicon, bronze, hard rolled silver or copper, platinum silver and german silver.

\* Spiral Springs → Space requirement is less than other types.

→ For most of the instruments, uniform scale phosphor bronze spiral springs are provided.

Flat spiral springs are used in almost all indicating instruments.

→ The inner end of this spring is attached to the spindle while the outer end is attached to a lever or arm which is actuated by a set of screws mounted on the control



At the front of the instrument so zero setting can be done.

→ The controlling torque provided by the instrument is directly proportional to the angular deflection of the pointer.

The controlling torque produced by spiral spring is given,

$$\tau_c = \frac{Ebt^3}{12L} \theta = Ks\theta$$

$$\tau_c \propto \theta$$

where  $t$  = thickness in meters  
 $E$  = Young's modulus of spring material

$b$  = depth in meters

$L$  = Length in meters.

Hence now deflecting torque is proportional to current

$$\tau_d \propto I$$

$K_s$  = Spring Constant

$$\text{At Equilibrium } \tau_d = \tau_c = \frac{Ebt^3}{12L}$$

$$I \propto \theta$$

Note: Thus the deflection is proportional to the current. Hence the scale of the instrument using Spring control is uniform.

When the current is removed, due to spring force the pointer comes back to initial position. The spring control is very popular and is used in almost all indicating instruments.

Comparison of controlling systems :-

Gravity Control	Spring Control
1. Adjustable small weight is used which produces the controlling torque.	Two hairsprings are used which exert controlling torque.

3. Controlling torque can be varied. The controlling torque is fixed.
4. The performance is not temperature dependent. The performance is temperature dependent.
5. The scale is non-uniform. The scale is uniform.
6. The readings can not be taken accurately. Readings can be taken very accurately.
7. The system must be used in vertical position only. The system need not be necessarily in vertical position.
8. Proper levelling is required. The levelling is not required.
9. Simple, cheap but delicate. Simple, rigid but costlier compared to gravity control.
10. Rarely used for indicating and portable instruments. Very popularly used in most of the instruments.

Damping system:

→ The deflecting torque provides some deflection and controlling torque acts in the opposite direction to that of deflecting torque.

→ So before coming to the rest, pointer always oscillates due to inertia, about the equilibrium position until pointer comes to rest final readings cannot be obtained.


→ So to bring the pointer to rest within short time damping system is required.

→ This system should provide damping torque only when the moving system is in motion.

- Damping torque is proportional to velocity of the moving system.
- The quickness with which the moving system settles into the final steady position depends on relative damping.
- If the moving system reaches to its final position rapidly but smoothly without oscillations the instrument is said to be critically damped.

- If the instrument is under damped the moving system will oscillate about the final steady position with a decreasing amplitude and will take some time to come to rest.

- While the instrument is said to be over damped if the moving system moves slowly to its final steady position. In over damped case the response of the system is very slow. In practice slightly underdamped systems are preferred.



The following methods are used to produce damping torque.

- ⇒ ① Air friction damping
- ② Fluid friction damping

### ③ Eddy current damping.

- ① Air friction damping.

- In this method of obtaining damping, a light aluminum piston is rigidly attached to the spindle and it is made to reciprocate inside an air chamber as shown in the figure.
- The piston moves to & fro in the camber when the

spindle rotates with small clearance b/w itself & the walls of the chamber which is closed at one end.

→ When the pointer moves clockwise i.e. upscale, the piston moves down wards. The air in the closed portion of the chamber expands & its pressure falls.

→ The pressure in the open portion of the chamber forces the piston upwards.

→ If the piston moves anticlockwise, the piston moves upward compressing the air above it. The increased air pressure forces the piston downwards.

→ Thus the motion of the pointer is opposed in either direction, with the result that oscillations of the pointer lie down, and the mean deflected position can be instantaneously noted.



### Advantages:-

→ Simple and cheap

→ no use of permanent magnets

→ used for m<sup>2</sup> and dynamometer type Instruments

③ fluid friction damping:-



→ Due to more viscosity of fluid more damping is provided.

### Advantages:-

oil Can be used for insulation purposes, Due to the up thrust of oil, the load on bearings are reduced

thus reducing frictional error.

Disadvantages:-

- Can be used for instruments which are in vertical position because of creeping of oil, instruments cannot be kept clean.

→ In this method damping is brought about by motion of metallic vanes inside a highly viscous liquid. The arrangement is as shown in fig.

→ Thin metallic vanes which are suitably shaped are suspended from the spindle and they are kept immersed in a highly viscous oil contained in a suitable vessel.

→ When the spindle rotates, the metallic vanes also move through the oil.

→ The frictional force between oil and the vanes is used to produce the damping torque.

→ However due to the high viscosity of the oil a torque which opposes the motion of the spindle is brought into play this is the damping torque.

→ Used only in electrostatic instruments


③ Eddy current damping:-

→ In this method damping is produced due to eddy currents induced in an aluminium disc

rigidly mounted aluminium on the spindle as shown in fig.

→ The disc is circular and it is so positioned that, when it rotates its edges

cut across the flux due to a small



→ When the spindle rotates, the aluminium disc also rotates along with it. Due to the flux of the magnet being cut across by the edge of the disc, eddy currents are induced in the disc.

→ Due to interaction b/w these Eddy currents & the flux producing them, a torque is set up.

→ According to Lenz's law the direction of this torque is such as to oppose the motion of the spindle hence it brings about damping.

Advantage :-



electromagnetic  
damping  
in temporary  
magnet

→ most effective and efficient method.

Drawback :-

→ Cannot be used in MI and dynamometer type instruments


~~Permanent magnet moving coil Instruments (PMMC)~~

→ The Permanent magnet moving coil instruments are most accurate type of dc measurements. The action of these instruments is based on the motoring principle.

→ When a current carrying coil is placed in the magnetic field produced by permanent magnet, the coil experiences a forced move.

→ As the coil is moving and the magnet is permanent the instrument is called permanent magnet moving coil instrument.

→ This basic principle is called D'Arsonval principle. The amount of force experienced by the coil is proportional to the current through the coil.



- The moving coil is either rectangular or circular.
- It has no. of turns of fine wire.
- The coil is suspended so that it is free to turn about its vertical axis.
- The coil is placed in uniform, horizontal and radial magnetic field of a permanent magnet in the shape of a horse-shoe.
- The iron core is spherical if the coil is circular and is cylindrical if the coil is rectangular.
- Due to iron core, the deflecting torque increases, easing the sensitivity of the instrument.
- The controlling torque is provided by two phosphor bronze hair springs.

- The damping torque is provided by Eddy current damping. It is obtained by movement of the aluminium former moving in the magnetic field of the permanent magnet.
- The pointer is carried by the spindle and it moves over a graduated scale. The pointer has high light weight so that it can deflect rapidly.
- The mirror is placed below the pointer to get the accurate reading by removing the parallax.
- The weight of the instrument is normally counter balanced by the weights situated diametrically opposite and rigidly connected to it.
- The scale markings of the basic d.c pmmc instruments are usually linearly spaced as the deflecting torque and hence the pointer deflection are directly proportional to the current passing through the coil.

Torque Equation:-

The Equation for the developed torque can be obtained from the basic law of the electromagnetic torque. The deflecting torque is given by:

$$T_d = N B A I$$

$T_d = \text{Force} \times \text{distance}$  force on each side of coil =  $N B I l$

$$T_d = N B I l \times d = N B I A$$

Where  $T_d$  = deflecting torque in N-m

$B$  = flux density in air gap,  $\text{wb}/\text{m}^2$

$N$  = No. of turns of the coil

$A$  = Effective coil area  $\text{m}^2$

$I$  = Current in the moving coil, Amperes.

$$T_d = GI$$

$$G = N B A = \text{constants}$$

The controlling torque is provided by the springs and is proportional to the angular deflection of the pointer.

$$T_c = k\theta$$

where  $T_c = \text{controlling torque}$  of the pointer

$$k = \text{Spring constant, Nm/rad (or) Nm/deg}$$


$$\theta = \text{Angular deflection, rad or deg}$$

For the final steady state position,  $T_d = T_c$

$$GI = k\theta$$

$$\theta = \left(\frac{G}{k}\right) I$$

$$I = \left(\frac{k}{G}\right) \theta$$



Note:- ① Thus the deflection is directly proportional to the current passing through the coil.

- ② As the direction of the current through the coil changes, the direction of the deflection of the pointer also changes. Hence such instruments are well suited for d.c measurements.

$$IAIN = 15$$

- ③ In the micro ammeters and milliammeters upto about 50mA, the entire current to be measured is passed through the coil. The springs carry current to the coil. Thus the current carrying capacity of the springs limits the currents which can be safely carried.

- ④ Most dc voltmeters are designed to produce full scale deflection with a current of 20, 10, 5 or 1mA.

⑤ The power requirement of PMMC instrument is very small typically of the order of  $25\text{mW}$  to  $800\text{mW}$ . Accuracy is generally of the order of  $\pm 2$  to  $5\%$  of the full scale reading.

### Advantages:-

1. It has uniform scale.
2. With a powerful magnet, its torque to weight ratio is very high so operating current is small.
3. The sensitivity is high.
4. It consumes low power of the order of  $25\text{mW}$  to  $800\text{mW}$ .
5. It has high accuracy.
6. Instrument is free from hysteresis error.
7. Extension of instrument range is possible.
8. Not affected by external magnetic fields called Stray magnetic fields.

### Disadvantages:-

1. Suitable for DC measurements only.
2. Ageing of permanent magnet, is the control springs introduces machining.
3. The coil is high due to delicate construction and accuracy machining.
4. The friction due to jewel-pivot suspension.

### Error in PMMC Instrument:-

→ The basic sources of errors in PMMC instruments

are friction, temperature and aging of various parts. To reduce the frictional errors of torque to weight is made very high.

- The most serious errors are produced by the heat generated or by changes in the temperature. This changes the resistance of the working coil causing large errors.
- The aging or permanent magnet and control springs also cause errors. The weakening of magnet and springs cause opposite errors.
- The weakening of magnet cause less deflection while weakening of the control springs cause large deflection for a particular value of current.
- The proper use of material and preageing during manufacturing can reduce the errors due to weakening of the control springs.

### Moving Iron Instruments:-


In this type of instruments [Ammeters and Voltmeters] the current carrying coil is stationary, but the iron core rotates hence it is called as moving iron (MI) instruments. These instruments are mostly used to measure the current and voltage in an alternating and direct current circuit. There are two types of moving iron instruments. Attractive Type: These operate on the principle of attraction of a single coil of soft iron into a magnetic field.

Repulsion type: These operate on the principle of repulsion between two adjacent iron pieces magnetized by the same magnetic field.

The Attraction type MI instruments.

Construction:-

- A MI instrument of the attraction type is shown in fig. It consists a fixed coil "C" of a copper wire mounted on a bobbin B.



→ The spindle [or moving system] has a suitably shaped soft iron piece rigidly fixed to it, and it is mounted eccentrically with respect to the fixed coil as shown → A pointer rigidly attached to the spindle can move over a graduated scale.

→ Controlling torque is provided by the spring  $S_p$  and damping is obtained by the piston and air motion of the piston  $P_p$

Working:- When current flows through the coil, the operating current fluxes through the coil.

- The operation of mi instruments depends upon the magnetic effect of electric current.
- When the instrument is connected in the circuit to measure currents or voltages, the operating current flows through the coil. Like a magnet and therefore it attracts the soft iron piece towards it, thus providing the deflecting

torque ( $T_d$ ).

- The deflecting torque causes the pointer attached to the moving system moves from zero position over a graduated scale.
- The deflecting torque depends upon the value and magnetic flux or in other words the current flowing through the coil.
- The spiral spring offers the controlling torque ( $T_c$ ) which depends upon the angle of twist.
- When the deflecting torque is equal to the controlling torque ( $T_d = T_c$ ) the pointer will come to rest at a position.
- The damping torque is provided by the air friction. A light aluminium piston is attached to the moving system. It moves in a fixed chamber.
- The chamber is closed at one end. It can also be provided with the help of vane attached to the moving system.
- The operating magnetic field in moving coil instruments is very weak. Hence eddy current damping not used since it requires a permanent magnet which would affect or distort the operating field.

~~Repulsion type of Instruments~~ - Due to repulsion effect


- These instruments have two vanes inside the coil, the one is fixed and other is movable.
- When the current flows in the coil, both the vanes are magnetized with like polarities induced on the same side. Hence due to the repulsion of like polarities, there is a force of repulsion between the two vanes causing

the movements of the moving vane.

→ Repulsion type instruments are most commonly used instruments. They are two types.

(i) Radial vane type.

(ii) Co-axial vane type.



→ Fig above shows the radial vane repulsion type instrument. Out of all the other moving iron mechanisms, this is the most sensitive and has most linear scale.


→ The two vanes are radial strips of iron. The fixed vane is attached to the coil.

→ The movable vane is attached to the spindle and suspended in the induction field of the coil. The needle of the instrument is attached to this vane.

→ Even though the current through the coil is alternating, there is always repulsion b/w the like poles of the fixed and the movable vane.

→ Hence the deflection is effectively proportional to the actual current and hence the scale is calibrated effectively, read amperes or volts. The calibration is accurate only for the frequency for which it is designed because the value is different for different frequencies concerned.

→ Fig shows the concentric vane repulsion-type instrument.



→ The instrument has a pointer and a scale graduated to the coil frame rigidly while the other can rotate freely inside the stationary frame.

→ Both the vanes are magnetised to the same polarity by the current in the coil.

→ Thus the movable vane rotates under the repulsive force along with the coil.

- As the movable vane is attached to the pivoted shaft, the repulsion results in a rotation of the shaft.
- The pointer deflection is proportional to the current in the coil.
- The concentric vane type instruments is moderately sensitive and the deflection is proportional to the square of the current through the coil. Thus the instrument is said to have Square Law response.
- Hence moving iron instruments can be used for both AC and DC measurements.

→ Due to square law response, the scale of the moving iron instrument is non-uniform.

#### ADVANTAGES:-

- The various advantages of moving iron instruments are
  - i) These instruments can be used for both A.C and D.C measurements.
  - \* The M.I Instruments are unpolarised instruments i.e. they are independent of direction of current.
  - ii) As the torque to weight ratio is high, errors due to the friction are very less.
  - 3) These are capable of giving good accuracy.
  - 4) The range (and) of instruments can be extended.
  - 5) These are no current carrying parts in the moving system. Hence these materials are extremely rugged and reliable.

- 1) The scale of the moving iron instrument is not up accurate readings are not possible at this end.
- 2) These are serious errors due to hysteresis, frequency changes and stray magnetic field.
- 3) power consumption is on higher side.
- 4) The increase in temperature increases the resistance of coil, decreases stiffness of the springs.

### Toque of Equation of moving Iron Instruments:

Consider a small increment in current supplied to the coil of the instrument. Due to this current is to be the deflection under the deflecting torque. Due to such deflection some mechanical work will be done.

mechanical work =  $\int F d\theta$   
 There will be a change in the energy stored in the magnetic field due to the change in inductance. This is because the vane tries to occupy the position of maximum deflection hence the force is always in such direction  $E_0$  as to increase the inductance of coil. The inductance is inversely proportional to the deflection in the magnetic circuit of coil.

Let us  $I =$  Initial Inductance

$L =$  Instrument Inductance

$\theta =$  Deflection to which spring

$dI =$  Increase in Current  
 no better gives change in deflection

In order to effect an increment  $dI$  in current, there must be an increment in the applied voltage given by

$$e = \frac{d(V)}{dt} \quad \text{from first principle}$$

$$= I \frac{dL}{dt} + L \frac{dI}{dt}$$

As both  $I$  &  $L$  are changing

The electrical energy supplied is given by,

$$eIdt = \left( I \frac{dL}{dt} + L \frac{dI}{dt} \right) Idt$$

$$= I^2 dt + IL dI$$

The stored energy increases from  $\frac{1}{2} L I^2$  to  $\frac{1}{2} (L+dI)(I+dI)$

$$\text{Hence the change in the stored Energy}$$

$$= \frac{1}{2} (L+dI)(I+dI)^2 - \frac{1}{2} L I^2$$

Neglecting higher order terms, this becomes,  $I+dI+1/2dI$

The energy supplied is nothing but increase in stored energy plus required for mechanical work done.

$$\therefore I^2 dL + IL dI = IL dI + \frac{1}{2} I^2 dL + T_d d\theta$$

$$T_d = \frac{1}{2} I^2 \frac{dL}{d\theta}$$

While the controlling torque is given by

$$T_c = k\theta$$

where  $k$  is spring constant

$$T_c = T_d$$

$$k\theta = \frac{1}{2} I^2 \frac{dL}{d\theta} \quad \text{under Equilibrium}$$

$$\theta = \frac{1}{2} \frac{I^2}{k} \frac{dL}{d\theta}$$

Thus the deflection is proportional to the square of the current through the coil. And the instrument gives square law response.

### Errors in moving iron Instruments :-

#### Errors with Both DC and AC :-

##### 1. Hysteresis Error:-

This error occurs as the value of flux density is different for the same current for ascending & descending values.

$$H_B \left( \frac{I_B}{f_B} + \frac{I_B}{f_B} E \right) = f_B I_B$$

This error can be minimized by making the iron parts small so that they demagnetize themselves quickly. It may produce 8 to 3% error. With the use of nickel iron alloys it is reduced to 0.05%.

##### 2. Temperature Error:-

The effect of temperature changes on moving iron instruments arises from the temperature co-efficient of spring. In voltmeter error are caused due to self-heating of coil. Series resistance.

This is deduced by series resistance

##### 3. Stray magnetic fields:-

The errors due to stray magnetic fields may be appreciable as the operating magnetic field is weak.

These errors can be minimized by using an iron case of a thin iron shield over the working part.

##### Errors with A.C Only

##### 4. Frequency Errors:-

decreases and deflection decreases then frequency increases.

To reduce this frequency error a capacitor is placed in parallel with ammeter.

Errors in MC Instruments:-

#### 1. Frictional Error:-

The error due to friction at the pivot in the jewel of an instrument can be reduced with proper and balancing.

The error due to friction at the pivot can be reduced with proper and balancing. The mechanical friction and core can be avoided by carefully winding the coil.

#### 2. Temperature Error:-

The heat produced due to  $I^2R$  loss in the coil is known as "Temperature Error". This increases resistance in temperature which increases the change in operating current.

This error can be minimised by designing the instrument by providing proper ventilation and cooling.

#### 3. Error due to weakening of permanent magnet:-

The weakening of permanent magnet with the time of usage causes the error in the reading.

This error can be minimised by proper ageing of magnet at the time of manufacturing.

#### 4. Error due to stray magnetic fields:-

Due to the presence of iron core in the working part the effects of external magnetic fields is increased.

This error can be minimised by proper ageing of the magnet at the time of manufacture.

#### 4. Error due to Stray magnetic fields:-

Due to the presence of iron core in the working part the effects of External magnetic fields get modified.

#### 5. Thermo-electric Error:-

The error due to thermo-electric emf's is known as "thermo electric error". This mainly occurs in shunted Ammeters and is due to uneven temperature distribution in the coil and junctions of the shunts.

This error can be minimized by using a material having a low-thermo-electric emf such as manganine etc.

#### Extension of Range:-

Any instruments whether it is mm or mc have a limitation of measuring capacity and to extend the capacity to higher ranges it is necessary to use shunts and multipliers.

#### Shunts:-

The range of an ammeter can be extended by connecting a low resistance called shunts parallel with ammeter. The shunts carries the extra current and allows only safe current to flow through the ammeter.

#### Properties:-

1. Low temperature Coefficient.
2. Low thermal emf with copper wire to shunts.
3. The resistance of shunts should not exceed 1 ohm.

→ Cohen heavy currents are to be measured in the major part so that it is bypassed through a low resistance called a "shunt".

Extension of Ammeter:

Let 'I' be the total current

to be measured

$R_m$  = Internal resistance of coil ( $\Omega$ )

$R_{sh}$  = Shunt Resistance ( $\Omega$ )

$I_m$  = Full scale deflection current (A)

$I_{sh}$  = Shunt current (A)

Since the two resistances  $R_{sh}$  and  $R_m$  are in parallel, the voltage drop across them is same.

$$I_{sh} R_{sh} = I_m R_m$$

$$R_{sh} = \frac{I_m R_m}{I_{sh}}$$

$$\text{but } I_{sh} = I - I_m$$

$$\therefore R_{sh} = \frac{I_m R_m}{I - I_m}$$

$$R_{sh} = \frac{(I_m + I_m m)}{I_m}$$

$$\frac{I_m^2 m}{I_m}$$

$$\text{where } m = \frac{I}{I_m}$$

$$m = \text{multiplying power} \rightarrow \text{ratio of total current to the current through the coil}$$

$$m = \frac{I}{I_m} = \frac{I}{I_m} + R_m$$

Thus, the resistance) increase the range of ammeter, the shunt resistance required is  $\frac{R_m}{(m-1)}$  times the basic meter resistance.

"manganin" is usually used for Shunts of d.c. instruments, it gives low value of thermal Emf with copper.

"Constantan" is a useful material for A.C. circuits.

Shunts for moving Iron Instruments.

M.I. Instruments can be built

for a range upto 50A since


in these instruments

moving parts do not carry

any current hence shunts

are not necessary except for very large currents. If a shunt is required to be used

the inductances of both meter coil and shunt must be considered.



The current in meter and shunt one in inverse ratio to their impedance.

$$\frac{I_{sh}}{I_m} = \sqrt{\frac{(R_m)^2 + (\omega L_m)^2}{(R_{sh})^2 + (\omega L_{sh})^2}} \rightarrow ①$$

From above equation it is clear that the ratio of two currents depends upon frequency.

In order to have same division of current through meter and shunt for all frequencies. The ratio of impedances must remain constant.

In order to make readings independent of the frequency

the time constant of meter and shunt should be equal.

$$\frac{L_{sh}}{R_{sh}} = \frac{L}{R}$$

The Range of moving iron ammeters for A.C applications can be extended through use of current transformers.

→ When the range of the instrument has to be extended for high voltage measurements, Voltmeter multipliers are used.

[A highly non inductive resistance - multipliers].

Voltmeter multipliers:

A basic meter voltmeter  $V_{fs-m}$  is converted into a voltmeter by supply voltage  $V$  connecting a series resistance  $R_s$  with it. This series resistance is known as a multiplier.

Let  $I_m$  = Full Scale deflection current of meter.

$R_m$  = Internal resistance of meter movements.

$R_s$  = Multiplier resistance.

$V$  = Voltage across the meter for current  $I_m$ .

$V$  = Full range voltage of instrument.

for the circuit

$$V = I_m (R_m + R_s)$$

$$V = I_m R_m + I_m R_s$$

$$\therefore R_s = \frac{V - I_m R_m}{I_m} = \frac{V}{I_m} - R_m$$

In terms of multiplying factor

$$m = \frac{V}{V_{fs-m}} = \frac{I_m (R_m + R_s)}{I_m R_m} = \frac{1 + R_s / R_m}{R_m}$$

Resistance of multipliers ( $R_s = (m-1)R_m$ )

Essential requirements of multipliers:

1. Resistance should not change with time.

2. The change in their resistance with temperature should be small.

3. They should be non-inductively wound for A.C. meter.

For A.C. operation, the inductance has to be taken into accounts.

Then  $I_m = \frac{V}{\sqrt{(R+R_m)^2 + \omega^2 L^2}}$


$$\Theta = I_m \sqrt{R_m^2 + \omega^2 L^2}$$

multiplying power  $m = \frac{V}{I_m} = \frac{(R+R_m)^2 + \omega^2 L^2}{\sqrt{R_m^2 + \omega^2 L^2}}$

From above equation it is evident that  $m$  will change with change in frequency. The multipliers may be shunted by a capacitor, in order to compensate error caused by change of "m" with change of frequency.

Gravity Control:-

The type of control consists of a small weight attached to the moving system. whose position is adjustable. This weight produces a controlling torque due to gravity, this weight is called control weight.




The figure shows the gravity control system. At the position of the pointer, the controlling torque is zero.

The position is shown as position A of the weight in the figure.

Electrodynamometer Type Instruments:-

The electrodynamometer type instruments is a transfer instrument. A transfer instrument is one which is calibrated with a d.c. source and used without any modifications for a.c. measurements such a transfer instrument has same accuracy for a.c and d.c measurements. The electrodynamometer type instruments are often used in a.c voltmeter and ammeters.



The various parts of the electrodynamometer type instrument

### Fixed coils:-

The necessary field required for the operation of the instrument is produced by the fixed coils. A uniform field is obtained near the centre of coil due to division of coil in two sections. These coils are air cored. Fixed coils are wound with fine wire for using as voltmeter, while for ammeters and wattmeter it is wound with heavy wire.


### Moving Coils:-

The moving coil is wound either as a self-sustaining coil or else on a non-metallic former. It metallic former

The damping torque is provided by air friction by a pair of aluminium vanes which are attached to the spindle at the bottom.


### ① Electrodynamometer as Ammeter:

for using electrodynamometer instrument as Ammeter fixed and moving coils are connected in series and carry the same direct current. A suitable shunt is connected to these coils to limit current through them upto desired limit.




② Electrodynamometer as Voltmeter:

The electro-dynamometer instruments can be used as a voltmeter by connecting the field and moving coils in most accurate type of voltmeter.



③ Electrodynamometer as Wattmeter:

(using electrodynamometer instrument as a wattmeter to measure the power) the fixed coil acts as a current coil and must be connected in series with the load. The moving coil acts as a voltage coil or pressure coil and must be connected across the supply terminals.



Torque Equation:

Let  $i_1$  = Instantaneous Value of Current in fixed coil.

$i_2$  = Instantaneous Value of Current in moving coil.

$L_1$  = Self Inductance of fixed coils.

$L_2$  = Self Inductance of moving coil.

$M$  = Mutual inductance b/w fixed and moving coils.

The Electrodynamometer instrument can be represented as equivalent circuit as shown.

The flux linkage of coil,


$$\phi_1 = L_1 i_1 + m_{12} i_2$$

flux Linkage of coil alone

$$\phi_2 = L_2 i_2 + m_{12} i_1$$

Now  $e_1 = \frac{d\phi_1}{dt}$ ,  $e_2 = \frac{d\phi_2}{dt}$

Electrical input (Voltage) energy =  $e_1 i_1 dt + e_2 i_2 dt$



$$\begin{aligned} \text{Electrical input (Voltage) energy} &= e_1 i_1 dt + e_2 i_2 dt \\ &= i_1 d\left[L_1 i_1 + m_{12} i_2\right] dt + i_2 d\left[L_2 i_2 + m_{12} i_1\right] dt \\ &= i_1 dL_1 i_1 dt + i_1^2 dL_1 + i_1 i_2 dm_{12} dt + i_1 i_2 dL_2 dt + i_2 dL_2 i_2 dt + i_2^2 dL_2 \\ &\quad + i_1 i_2 dm_{12} dt \rightarrow ① \end{aligned}$$

The energy stored in magnetic field due to  $L_1$ ,  $L_2$  and  $M$  is given by.

$$\text{Energy stored} = \frac{1}{2} L_1 i_1^2 + \frac{1}{2} L_2 i_2^2 + i_1 i_2 M$$

$$\begin{aligned} \text{Change in stored energy} &= d\left[\frac{1}{2} L_1 i_1^2 + \frac{1}{2} L_2 i_2^2 + i_1 i_2 M\right] \\ &= i_1 L_1 di_1 + \frac{1}{2} i_1^2 dL_1 + i_2 L_2 di_2 + \frac{1}{2} i_2^2 dL_2 + i_1 M di_2 + i_2 \\ &\quad + i_1 i_2 dM \rightarrow ② \end{aligned}$$

From the principle of conservation of energy

Energy input = Energy stored + mechanical energy

$$\text{Mechanical Energy} = \text{Energy Stored} - \text{Energy Input}$$

Subtracting Eq ② from Eq ①

$$\text{Mechanical Energy} = \frac{1}{2} i_1^2 di_1 + \frac{1}{2} i_2^2 dL_2 + i_1 i_2 dM$$

$\frac{d\theta}{dt}$  are zero.

$$\text{Mechanical energy} = \frac{1}{2} i_1^2 dM$$

If  $T_d$  is the instantaneous deflecting torque,  $\theta$  is the change in the deflection then,

$$\text{mechanical energy} = \text{mechanical work done}$$

$$T_d \cdot \frac{1}{2} \theta^2 = \frac{mb}{eb} \cdot \frac{1}{2} \theta^2 = BT$$

$$T_d = \frac{1}{2} i_1^2 \frac{dm}{d\theta}$$

This is the expression for the instantaneous deflecting torque operation of deflecting torque in a.c and d.c

$$T_d = \frac{1}{2} i_1 i_2 \frac{dm}{d\theta}$$

For dc currents  $i_1$  and  $i_2$

$$T_d = i_1 i_2 \frac{dm}{d\theta}$$

$$\frac{mb}{eb} \frac{d\theta}{dt} = \text{provided}$$

The controlling torque is provided by springs hence

$$T_c = k\theta$$

$$T_d = T_c$$

$$i_1 i_2 \frac{dm}{d\theta} = k\theta$$

$$\theta = \frac{i_1 i_2}{k} \frac{dm}{d\theta}$$

Thus the deflection is proportional to the product of the two currents and the rate of change of mutual inductance.

along with this it is also proportional to the ratio of the two currents.

In a.c operation, the total deflecting torque over a cycle must be obtained by integrating  $T_d$  over one period.

Average deflecting torque over one cycle is

$$T_d = \frac{1}{T} \int_0^T T_d dt$$

$$T_d = \frac{dm}{d\theta} \frac{1}{T} \int_0^T i_1 i_2 dt$$

Now if the two currents are sinusoidal and displaced by a phase angle  $\phi$  then

$$i_1 = I_m \sin \omega t$$

$$i_2 = I_m \sin(\omega t + \phi)$$

$$T_d = \frac{dm}{d\theta} \cdot \frac{1}{2\pi} \int_0^{2\pi} I_m \sin \omega t \cdot I_m \sin(\omega t + \phi) d(\omega t)$$

$$= \left( \frac{I_m I_m}{2} \right) \cos \phi \frac{dm}{d\theta}$$

$$mb \cdot 2\pi = bt$$

$$btvorg = I_1 I_2 \cos \phi \frac{dm}{d\theta}$$

Where  $I_1, I_2$  are the rms values of the two currents

as

$$I_1 = \frac{I_m}{\sqrt{2}} \quad \text{and} \quad I_2 = \frac{I_m}{\sqrt{2}}$$

$$T_c = k\theta \frac{mb}{\theta b}$$

Hence steady state  $T_c = T_d$

$$\frac{mb}{\theta b} \frac{I_1 I_2 \cos \phi \frac{dm}{d\theta}}{I_1 I_2} = k\theta$$

$$\boxed{\theta = \frac{I_1 I_2}{K} \cos \phi \frac{dm}{d\theta}}$$

Thus the deflection is decided by the product of values of two currents, cosine of the phase angle

(power factor) and rate of change of mutual inductance.

Advantages:-

1. They have a precision grade accuracy.
2. used for both a.c and d.c , they are also used as transfer instruments.
3. free from hysteresis error.
4. Low Power Consumption.
5. Light in weight.

Disadvantages:-

1. They are more expensive.
2. They have a non-uniform scale.
3. These instruments have low sensitivity due to a low torque to weight ratio.
4. These instruments are sensitive to overloads and mechanical inputs.

Errors in Electrodynamometer

1. Torque to weight ratio:-

To have reasonable deflecting torque, mass of the moving coil must be large enough. Thus  $\text{mmf} = \text{No. of turns} \times \text{current}$

through moving coil should be high. No. of turns should be large. Current can not be high because it cause excessive heatings and springs large no. of turns in this only option. This reduces torque.

2. Frequency errors:-

The changes in the frequency causes to changes self

inductances of moving coil and fixed coil. This causes error in reading. This can be reduced by having equal time constants for both fixed and moving coil circuits.

### 3. Eddy Current Errors:

In metal parts of the instrument the eddy current

interact with the instruments current to cause change in the deflecting torque, to cause error. Hence metal parts should be kept as minimum as possible.

### 4. Stray magnetic field errors:

Operating field in electrodynamic instrument is very weak. Hence external magnetic field can interact with operating field to cause change in the deflection, causing the error. To reduce this error, the shields must be used for the instruments.

### 5. Temperature Error:

The temperature errors are caused due to the changes in the heating of the coil, which causes compensation of the coil. Thus temperature compensating resistor

can be used in the precise instrument to eliminate the temperature errors.

Suppose if there is a coil with two springs supporting it. If one spring is heated, then the other spring will contract to eliminate the effect of temperature.

Thus supports of current carrying coil will expand

## MEASUREMENT OF POWER AND ENERGY

Syllabus: Phasor addition to proof of principle


Principal of operation of EDM-type wattmeters - Errors and compensation - L PF and CPF types - measurement of three phase power by two and three wattmeters - single phase induction type energy meter - principle of operation = Errors and compensations in energy meters - three phase energy meter.

at bottom - in line showing connection wires and ot end  
Single phase Electrodynamometer-type wattmeter

→ An electrodynamometer type wattmeter is used to measure power.

→ It has two coils, fixed coil which is current coil and moving coil which is pressure coil or voltage coil.

→ The current coil carries the current of the circuit while pressure coil carries current proportional to the voltage in the circuit. This is achieved by connecting a series resistance in voltage circuit.



Electrodynamometer voltmeter

Let  $i_C$  = Current through current coil

(2)  $i_C = \frac{V}{R}$  Current through pressure coil

$R$  = Series resistance

$V$  = RMS value of supply voltage

$I = \text{RMS value of current}$

Torque Equation

According to theory of electro-dynamometer it

$$T = \frac{1}{2} I^2 R_m \frac{dm}{d\theta} \rightarrow ①$$

Let  $V = \text{Instantaneous voltage}$

$$\text{Voltage across pressure coil} = V_m \sin \omega t$$

$$\text{Current through coil} = \sqrt{2} V \sin \omega t \rightarrow ②$$

Due to high series resistance, pressure coil is purely resistive.

Therefore the Current  $I_{pc}$  is in phase with "V".  
coil is purely resistive.

$$I_{pc} = \text{Instantaneous Value}$$

$$= \frac{V}{R_p} \text{ where } R_p = R_{pc} + R$$

$$I_{pc} = \frac{\sqrt{2} V \sin \omega t}{R_p}$$

$$= \sqrt{2} I_{pc} \sin \omega t \rightarrow ③$$

If the current coil current lags the voltage angle  $\phi$  then its instantaneous value is

$$i_c = \sqrt{2} I_{pc} \sin(\omega t - \phi) \rightarrow ④$$

$$T_i = [\sqrt{2} I_{pc} \sin \omega t] [\sqrt{2} I_{pc} \sin(\omega t - \phi)] \frac{dm}{d\theta}$$

$$= 2 I_{pc}^2 \sin \omega t \sin(\omega t - \phi) \frac{dm}{d\theta}$$

$$= 2 I_{pc}^2 [ \cos \phi - \cos(\omega t - \phi) ] \frac{dm}{d\theta} \rightarrow ⑤$$

Thus Instantaneous torque has one component of power

which varies twice the frequency of current & voltage

$T_d = \text{Average deflecting Torque}$

$$T_d = \frac{1}{T} \int_0^T i_{id}(wt) dt$$

$$= \frac{1}{T} \int_0^T I_c I_{pc} [\cos\phi - \cos(\omega t - \phi)] \frac{dm}{d\theta} d(wt)$$

$$T_d = I_c I_{pc} \cos\phi \frac{dm}{d\theta} \rightarrow ⑥$$

$$\text{where } I_{pc} = \frac{N \cdot g}{R_p}$$

for Spring Control System  $T_d = k\theta \rightarrow ⑦$

$$\text{Let } T_d = I_c \left[ \text{At Equilibrium} \right]$$

$$I_c I_{pc} \cos\phi \frac{dm}{d\theta} = k\theta$$

$$\theta = \frac{1}{k} I_c I_{pc} \cos\phi \frac{dm}{d\theta}$$

$$= k_1 I_c I_{pc} \cos\phi \rightarrow ⑧$$

$$\text{where } k_1 = \frac{1}{k} \frac{dm}{d\theta}$$

$$\therefore \theta = k_1 I_c \frac{V}{R_p} \cos\phi = k_2 P \rightarrow ⑨$$

$$\text{where } k_2 = \frac{k_1}{R_p} \text{ & } P = V I_c \cos\phi \text{ is power}$$

$$\theta \propto P \rightarrow ⑩ \quad \theta + \phi = \phi \text{ in terms}$$

Thus wattmeter deflection when calibrated gives the power consumption of the circuit.

Errors in Electrodynamometer Wattmeter:-

1. Error due to pressure coil inductance:

Let  $r_p$  = resistance of pressure coil

(Inductance of pressure coil.

$R_p$  = Total resistance of pressure coil.

$$= r_p + z$$

$V$  = Voltage applied to pressure coil current

$I$  = Current in the current coil circuit

$I_p$  = Current in pressure coil circuit.

$Z_p$  = Impedance of pressure coil circuit


$$= \sqrt{(R+r_p)^2 + (wL)^2}$$

→ In an ideal wattmeter that the current in the pressure coil is in phase with applied voltage.

→ If the pressure coil of wattmeter has an inductance the current in it will lag voltage by an angle  $\beta$ .

$$\beta = \tan^{-1} \left( \frac{wL}{R_p} \right)$$

$$= \tan^{-1} \left( \frac{wL}{R+r_p} \right)$$



→ For the lagging p.f. the angle b/w current coil current in the pressure coil circuit is less than  $\phi$ .

→ The angle b/w pressure coil current & current coil current is  $\phi' = \phi - \beta$

$$\text{Actual wattmeter reading} = \frac{(V \cdot I)}{K} \cos \phi \frac{dm}{de}$$

$$= \frac{V \cdot I}{Z_p \cdot K} \cos(\phi - \beta) dm$$

$$= \frac{V \cdot I}{K \cdot \left( \frac{R_p}{\cos \phi} \right)} \cos(\phi - \beta) \frac{dm}{de}$$

$$= \frac{V \cdot I}{K \cdot R_p} \cos(\phi - \beta) \cos(dm/de)$$

If the inductance is zero i.e.  $Z_p = R_p$  &  $\beta = 0$  then its wattmeter will read true power.

$$\text{True power} = \frac{I_p \cdot I}{K} \cos \phi \frac{dm}{d\theta}$$

$$= \frac{\sqrt{I} \cos \phi}{K} \frac{dm}{d\theta}$$

true power

$$\frac{\text{Wattmeter reading}}{\text{true power}} = \frac{\sqrt{I} \cos \phi}{K \cdot R_p} \cdot \frac{dm}{d\theta} \times \frac{K \cdot R_p}{\sqrt{I} \cos(\phi - \beta) \cos \beta} \frac{dm}{d\theta}$$

$$= \frac{\cos \phi}{\cos(\phi - \beta) \cos \beta}$$

$$\text{True power} = \frac{\cos \phi}{\cos(\phi - \beta) \cos \beta} \text{ actual wattmeter reading}$$

Correction factor =  $\frac{\cos \phi}{\cos(\phi - \beta) \cos \beta}$

→ from the vector diagram for the lagging loads.

wattmeter will read high due to the effect of pressure coil inductance.

→ For leading load, wattmeter will read low value due to effect and pressure coil inductance.

Correction factor for leading load =  $\frac{\cos \phi}{\cos \beta \cos \phi \cos \beta \cos(\phi + \beta)}$


$$\text{Error} = \tan \phi \tan \beta \times \sqrt{I} \cos \phi = \sqrt{I} \sin \phi \tan \beta$$

→ From the above it is clear that error is serious at low power factor.

Compensation :-

many wattmeter are compensated for inductance of pressure coil current by connecting a capacitor in parallel to a portion

of series resistance as shown in figure.



$$\text{Total impedance} = Z_p = (R_p + jL) + jwL + j - jwC_r^2$$

If the value of circuit constants are chosen as  
 $\omega C_r^2 \ll 1$   
then  $Z_p \approx R_p + jL + jwL + j - jwC_r^2 \approx R_p + jw(L - C_r^2)$

If we make  $L - C_r^2 = 0$  then  $Z_p \approx R_p$  &  $B = 0$

Hence error due to pressure coil is almost eliminated

### ② Errors caused by stray magnetic fields:

The dynamometer wattmeter is particularly capable of the influence of stray magnetic fields. Hence the instrument is effectively shielded magnetically so that the operating system is free from adverse effects due to external magnetic fields.

### ③ Errors caused by mutual inductance:

The mutual inductance between current coil and voltage coil also causes errors, but these are negligible at low frequency.  $\phi_{AB} IV = \Phi_{AB} IV \times 8 \pi / 10^7 = 0$


This is minimised by properly designing the coil such that the coils are always in a position of zero mutual inductance.

④ Errors due to Eddy currents :-  
 When the current coil carries alternating current and alternating flux is set up and this induces eddy current in solid metal parts of the operating system and also in the conductors of the current coil, due to this errors get introduced.

This can be minimised by avoiding solid metal parts having standard conductors.

⑤ Errors caused by Capacitance of potential coil :-  
 Since a high series resistance is incorporated in the voltage coil circuit, this resistor has inter-turn capacitance opposite to that of the voltage coil inductance, and if the two effects oppose each other, the net error may be zero.

⑥ Error due to method of connection :-



Because of the power loss in the current and pressure coils, error is introduced in the measurement of power.

→ In fig (i) pressure coil is connected on the supply side and therefore the voltage applied to the pressure coil is the voltage across the load plus voltage drop across current coil. Thus wattmeter measure power loss in its current coil in addition to power consumed by load.

power indicated by wattmeter = power consumed by load  
 from wattmeter + power loss in current coil ( $I^2 R_c$ )  
 → If the wattmeter connections are shown in fig (2) the  
 current coil is on supply side and hence it carries pressure  
 coil current plus the load current. Thus wattmeter reads  
 in addition to power consumed in load, the power lost  
 in pressure coil.

Power indicated by

$$\text{Wattmeter reading} \rightarrow \frac{\text{Power consumed by load}}{\text{pressure coil}} + \frac{\text{Power loss in pressure coil}}{\text{circuit}} = \frac{V^2}{R_p}$$

If any circuit is operating at low power factor then  
 power in that circuit is difficult to measure with  
 ordinary electrodynamometer wattmeter. The reading of watt-  
 meter is accurate on account of following reasons.


- 1) The deflecting torque on the moving system is small as the power factor is low even though the current and pressure coils are fully excited.
- 2) The inductance of pressure coil introduces considerable error at low power factor.

In order to get accurate reading from the wattmeter when it is measuring low power, extra adjustments are required to be made so that there will be compensation of the errors.

Compensation of the errors:

When the power to be measured is low then the current in the circuit is high as the power-factor is low. Thus in this case pressure coil cannot be connected to supply side otherwise large error will be produced because of large currents flowing in current coil and corresponding power low in current coil circuit is measured by wattmeter.

If the pressure coil is connected to load side power consumed by pressure in comparison with power to be measured which is small. Hence it is necessary to compensate for pressure coil current in low power factor wattmeter. The compensated wattmeter is shown in figure (i).




### 1) Pressure coil current :-

→ The pressure coil circuit is designed to have low value of resistance.

→ So that the current flowing through it is increased to an increased operating torque.


→ The pressure coil current in a low power factor wattmeter



may differ as much as 10 times or the value employed for high power factor. ~~so that reading will be dependent on load~~

② Compensation for pressure coil current :-

The power being measured in a LPF circuit is small and current is high on account of LPF connecting. It cannot be used because owing to large load current.



There would be a large power loss in the current coil and therefore the wattmeter will give a large error.

If we used connection of fig (ii) the power loss in the PC circuit is included in the reading given by wattmeter.

Thus with this connection also the wattmeter will give a serious errors as the power loss in the power coil may be a large percentage of power being measured.

∴ The compensating coil is wound on current coil to compensate for the pressure coil current in a low power factor wattmeter, as shown in fig (a).

③ Compensation for Inductance of pressure coil :-

The error caused by pressure coil inductance is  $\tan \beta$ . The LPF, the value of  $\phi$  is large; therefore error is large. Error is compensated by connecting capacitor as a part of series resistance in the pressure coil circuit as shown in fig (b).

shown in fig (b) and in fig (c) showing soft

(e) small control torque

LPF Wattmeter are designed with to have a small control torque so that they give full scale deflection for power factor as low as 0.1.

Measurement of power in three phase circuits

There are three methods power in three phase circuits. They are

i) Three wattmeter method.

ii) Two wattmeter method.

iii) One wattmeter method.

i) Three wattmeter method

The three wattmeter method is

employed for a 3 phase

a wire system one shown in

figure.

In this case the common point  $w_2$  is 3-wattmeter

N of pressure coils and the neutral  $\delta$  of the load coincide

and therefore.

$$V=0$$

and  $V_A = V_B + V_C$

$$\text{and } V_A = V_A^1 + V_B^1 + V_C^1$$

Instantaneous power of the load

at any instant

$$P = V_A I_A + V_B I_B + V_C I_C$$

to measure three wattmeters

Hence these three wattmeters measure the power of the load.


ii) Two wattmeter method

In a three wire system we require 3 elements but

if we make the common points of the pressure coils coincide with all the three phases we will require only  $P = 2$  elements.

Instantaneous power consumed by load =  $V_A i_A + V_B i_B + V_C i_C$

Let us consider two wattmeters connected to measure power in 3 phase circuits as shown below.



Two wattmeter method (Y connection)

STAR (WYE) connections:

In this Connections

Instantaneous reading of w<sub>1</sub> wattmeter  $w_1 = P_A (V_A - V_C)$

Instantaneous reading of w<sub>2</sub> wattmeter  $w_2 = P_B (V_B - V_C)$

Sum of two readings  $= w_1 + w_2 = i_A (V_A - V_C) + i_B (V_B - V_C)$

From fig ①  $= V_A i_A + V_B i_B - V_C (i_A + i_B)$

Applying Kirchhoff's law

$$i_A + i_B + i_C = 0 \quad (1) \quad i_C = -(i_A + i_B)$$

$$\therefore w_1 + w_2 = V_A i_A + V_B i_B + V_C i_C$$

Therefore the sum of the two wattmeter reading is equal to the power consumed by the load. This is irrespective of load whether it is balanced or unbalanced.

DELTA CONNECTION

Instantaneous reading of one wattmeter  $w_1 = V_A i_A + V_B i_B + V_C i_C$

Instantaneous reading of w<sub>2</sub> wattmeter  $w_2 = V_B i_B + V_C i_C + V_A i_A$

$$= V_B i_B + V_C i_C - P_A (V_B + V_C)$$

from fig 3

Applying Kirchhoff's Voltage Law

$$V_A + V_B + V_C = 0$$

$$V_A = -(V_B + V_C)$$

$$\therefore (V_A + V_C) = V_A i_A + V_B i_B + V_C i_C$$

Therefore the sum of the two wattmeter readings is equal to the power consumed by the load. This is irrespective of load whether it is balanced or unbalanced.

FOR BALANCED LOAD

The figure shows the phasor diagram for a balanced star connected load.

Let  $V_A, V_B, V_C$  be the rms values of phase voltages and  $i_A, i_B, i_C$  the rms values of current.

values of phase voltage and  $i_A, i_B, i_C$  the rms values of current

The load is balanced therefore phase voltages  $V_A = V_B = V_C = \frac{V_L}{\sqrt{3}}$

Line Voltage  $V_{AC} = V_{BC} = V_{AB} = V_L$

Line Currents  $I_A = I_B = I_C = I$  = phase currents.

power factor  $= \cos \phi$

The current through wattmeter  $w_1$  is  $i_A$  and voltage across pressure coil is  $V_{AC}$ . It leads  $V_{AC}$  by an angle  $(30^\circ - \phi)$ .

Reading of  $w_1$  wattmeter

$$C_{w1} = V_{AC} i_A \cos (30^\circ - \phi) = V_L i_L \cos (30^\circ - \phi)$$

The current through wattmeter  $w_2$  is  $i_B$  and voltage across

pressure (AC) is  $V_{BC}$  it leads  $V_{BC}$  by an angle  $(30^\circ + \phi)$ .

Total power consumed by loads =  $w = w_1 + w_2$

$$= w = V_L I_L \cos(30 - \phi) + V_E I_E \cos(30 + \phi)$$

$$w_1/w_2 = \sqrt{3} V_L I_L \cos \phi \text{ on plane}$$

Dif b/w wattmeter readings

$$w_1 - w_2 = V_L I_L \cos(30 - \phi) - V_L I_L \cos(30 + \phi)$$

$$= V_L I_L \sin \phi$$

$$\frac{w_1 - w_2}{V_L I_L \cos \phi} = \sin \phi$$

$$\Rightarrow \tan \phi = \frac{\sqrt{3}(w_1 - w_2)}{w_1 + w_2}$$

$$\Rightarrow \phi = \tan^{-1} \left( \frac{\sqrt{3}(w_1 - w_2)}{w_1 + w_2} \right)$$

$$\text{power-factor } \cos \phi = \cos \left( \tan^{-1} \left( \frac{\sqrt{3}(w_1 - w_2)}{w_1 + w_2} \right) \right)$$

## MEASUREMENT OF ENERGY

### Introduction:-

Energy is defined as the work done over a time interval.

The energy is defined as the power delivered over a time interval.

$$\text{Energy} = \text{Power} \times \text{Time} = P \times t$$

The electrical energy is defined as the work done over a time interval  $t$  and mathematically expressed as,

$$E = \int_0^t (\text{power}) dt = \int_0^t V_i I_i dt$$

The energy is measured in joules (J) or Watt-sec (W), Watt-

hour (Wh), kilo watt-hour (kWh)

1 Wh = 1 J = 1000 Joules

1 kWh = 1000 Wh = 1000 J

## SINGLE PHASE INDUCTION TYPE ENERGY METER

most commonly used energy meters are induction type instruments. Energy meter is an integrating instrument which measures quantity of electricity. These meters record the energy in kilowatt-hours (kwh).

\* The working principle of induction type EM is induction is on the production of Eddy currents in the moving system by the alternating fluxes. The interaction of produced eddy currents in the moving system produces driving torque, due to this rotate to record the energy. This Energy meter there is no controlling torque. due to this the disc is continuously rotates.

### Construction:-

There are four main parts

1. Driving System
2. moving System
3. Braking System
4. Registering System.

### Driving System:-

The driving system consists of two electromagnets. This electromagnets core is made up of silicon steel laminations.

The one electromagnet is series coil called Current coil, is excited by load current.

The another electromagnet is connected across the supply and it carries current proportional to supply voltage. This is called pressure coil.

These coil called Series and shunt magnets respectively.

### Moving System:-

Light aluminium disc mounted in a light alloy shaft is the main part of moving system. This positioned in two series and shunt magnet. It is supported by jewel bearings and runs a hard end steel pivot here there is no springs and controlling torque.


### 3. Braking System:-

A permanent magnet is placed near the aluminium disc for braking mechanism. It produces iron fields, when disc moves in this field the braking torque is obtained. The position of magnet is adjustable for different radial positions. So this magnet is called braking magnet.

### 4. Registering mechanism:-

It records continuously a number which is proportional to the revolutions made by the aluminium disc. For suitable system gears and pointers. These pointers are rotated on round dials which are equally marked with equal divisions.

In generally pointer type registering mechanism is used. These one all shown in below figure.



Operation: -

The Shunt magnet  $m_2$  which is connected across the supply, it carries Current proportional to the Voltage. Series magnet  $m_1$  carries Current coil which carries the load current. Both these coils produce alternating fluxes  $\phi_{sh}$  and  $\phi_s$  respectively. These fluxes are proportional to currents in their coils. These fluxes link with the disc and induces Emf (in it)  $200 \text{ mV} \text{ at } 50 \text{ Hz}$ .

Due to these Emfs eddy currents are induced in the disc due to the eddy currents in one coil to flux in another coil. Thus the portion of the disc experiences a mechanical force and due to motor action disc rotates. The speed of the disc is controlled by the shaped magnets cutting breaking magnets.

Torque Equation: -

$$\text{Let } [V = \text{Supply Voltage} = 200] \text{ IV at } 50 \text{ Hz}$$

$I$  = Load current

$$= 200 (0.08) = \text{Current coil current}$$

$I_p$  = pressure coil current

$$[\Delta = \text{phase angle between } I_p \text{ and } I] \text{ IV at } 50 \text{ Hz}$$

$$\Delta \approx 90^\circ$$

$$[200 \text{ mV} \text{ at } 50 \text{ Hz}]$$

$E_{ep} = \text{Eddy Emf induced due to } \phi_p$

$E_{es} = \text{Eddy Emf induced due to } \phi_s$

$\alpha = \text{phase angle of eddy currents.}$

$I_{ep} = \text{Eddy Current due to } E_{ep}$

$I_{es} = \text{Eddy Current due to } E_{es}$

Here the current  $I_p$  lags  $V$  by  $\Delta$  and  $\Delta$  is made  $90^\circ$  using

the Copper Shading bands, the Currents  $I$ ,  $I_p$  lags by  $\phi$  which depends on the loads, the flux  $\phi_{sh}$  and  $I$  are inphase, the  $E_{ep}$

lags  $\phi_p$  and  $E_{es}$  lags  $\phi_s$  by  $90^\circ$  respectively. The Eddy current

$I_{es}$  and  $I_{ep}$  lags and  $E_{ep}$  respectively by the angle  $\alpha$ .

The interaction b/w  $\phi_p$  and  $I_{es}$  produces torque.

And the interaction b/w  $\phi_s$  and  $I_{ep}$  produces torque  $T_2$ .

Phasor diagram for 1- $\phi$  induction type energy meter.

$$T_2 \propto \phi_s I_{ep} \cos(\phi_s - \phi_p)$$

From phasor diagram  $\phi_p - \phi_s = \alpha + \phi$

$$\phi_s - \phi_p = 180^\circ - \phi + \alpha$$

Deflecting torque  $T_d \propto T_2 - T_1$  [By  $\Delta$  rule]

$$T_d \propto \{ \phi_p I_{es} \cos(\alpha + \phi) \} - \phi_s I_{ep} \cos(180^\circ - \phi + \alpha)$$

$$T_d \propto \{ \phi_p I_{es} \cos(\alpha + \phi) \} - \phi_s I_{ep} \cos(180^\circ - \phi + \alpha)$$

$$\propto \{ \cos(\alpha + \phi) - \cos(180^\circ - \phi + \alpha) \}$$

$$\propto \{ \cos\alpha \cos\phi - \sin\alpha \sin\phi - (\cos(180^\circ - \phi) \cos\alpha - \sin(180^\circ - \phi) \sin\alpha) \}$$

$$\propto \{ \cos\alpha \cos\phi - \sin\alpha \sin\phi + \cos\alpha \cos\phi + \sin\alpha \sin\phi \}$$

$$T_d \propto \{ 2 \cos\alpha \cos\phi \}$$

$$T_d = K_1 V_I \cos\phi \quad [! \cos\alpha \text{ is constant}]$$

Thus the deflecting torque is proportional to the true power in the circuit.


The braking torque is due to eddy currents induced in the

aluminum disc, the magnitude of the currents is proportional to

the speed  $N$  of the disc, here the braking torque  $T_b$  is also

proportional to this speed  $N$ , i.e.  $T_b = K_2 N$

For study speed of rotation  $T_d = T_b$ .



$$KVI \cos\phi = k_A N$$

$$N = K VI \cos\phi = K [power]$$

The total No. of revolution =  $\int_0^t N dt = \int_0^t K (\text{power}) dt$

Total No. of revolution =  $K \int_0^t pdt = K \text{ energy}$

Thus the no. of revolutions of the disc in a given time is the energy consumption by the circuit in that time.

$$K = \text{meter Constant} = \frac{N}{\text{energy}} \text{ or } \frac{\text{No. of revolutions}}{\text{kwh}}$$

Thus the no. of revolutions of the disc per kWh of Energy

Consumption is called meter constant.

Advantages of Induction Type Energy meter :-

1. Its construction is simple and strong.
2. It is cheap in cost.
3. It has high torque to weight ratio, so frictional errors are less and we can get accurate reading.
4. It has more accuracy.
5. It requires less maintenance.
6. Its range can be extended with the help of instrument transformer's

Disadvantages:-

1. It can be used only for a.c Circuits.
2. The creeping can cause errors.
3. Lack of symmetry in magnetic circuit may cause errors.

## Errors and their Compensations in F of Energy meter:-

### 1. Phase Error:-

It is necessary that the energy meter should give correct reading on all power factors, which is only possible when the field set up by shunt magnet lags behind the applied voltage by  $90^\circ$ . But the flux due to shunt magnet does not lag behind the applied voltage exactly by  $90^\circ$  because of winding resistance and iron losses.

Compensation:- The flux in the shunt magnet can be made to lag behind the supply voltage by exactly  $90^\circ$  by adjusting the position of shading band placed round the lower end of the shunt magnet.

This adjustment is known as lag compensation or power factor compensation.

### 2. Speed Error:-

Sometimes the speed of the meter is either fast or slow, resulting in the wrong recording of energy consumption.

### Compensation:-

An error in the speed of the meter when tested on non-inductive load can be eliminated by correctly adjusting the position of the brake magnet. Movement of the brake magnet in the direction of the spindle will reduce the braking torque and vice-versa.

### 3. Friction Compensation (or) Friction Error:-

Frictional forces at the rotor bearings in the counting (or r.t.) mechanism cause noticeable error especially at high load. At light loads, the torque due to friction is considerably less than the braking torque exerted on the disc rotor so

friction torque is not proportional to the speed but is roughly constant. It can cause considerable error in meter reading due to non-linearity caused by the ratio.

### Compensation:-

This error can be reduced to an unimportant level by making the ratio of the shunt magnet flux  $\phi_2$  and series magnet flux  $\phi_1$  large with the help of two shading bands. These bands embrace the flux contained in the two outer limbs of the shunt magnet and thus eddy currents are induced in them which cause a phase displacement b/w the enclosed flux and the main gap flux. As a result, a small driving torque is exerted on the disc motor, this torque being adjusted by variation of the positions of these bands to compensate for friction on the instrument. Correctness of friction compensation is achieved by running the meter at high load of about 8 to 10% of full load when the disc should rotate correctly. Over compensation leads to creep. This compensation is known as light load compensation.

### 4. Creeping:-

Sometimes the disc of the energy meter make slow but continuous rotation at no load i.e., when the potential coil is excited but with no current flowing in the load. This is called creeping. This error may be caused due to over compensation of friction, excessive supply voltage, vibrations, stray magnetic fields etc. Compensation :-

In order to prevent this creeping on no load two holes or slots are drilled in the disc on opposite sides.

the spindle. This causes sufficient distortion of the disc so that the disc tends to remain stationary when one of the holes comes under one of the shunt magnet.

### 5. Temperature Errors:-

The error due to variation in temperature are very small because the various errors produce tend to neutralise one another. The air gap between the two magnets will also change due to variation in temperature.

The resistance of the disc of the potential coil and choice of magnetic circuit of the strength of break magnet are affected by the changes in temperature. Therefore great care is exercised in the design of the meter to eliminate the errors due to temperature variations.

### Frequency Variations:-

The meter is designed to give minimum error at a particular frequency (50 Hz). If the supply frequency changes, the reactance of the coils also changes resulting in small error.

### Voltage Variations:-

The error due to variation voltage is very small [usually 0.5% to 0.6%]. This can be eliminated by the proper design of the magnetic circuit of the shunt magnet.

Three phase Energy meter:- based on four wires system.  
→ In a three phase, four wire system, the measurement of energy is to be carried out by a three phase energy meter.

→ In a three phase, three wire system, the energy measured is shared out between the two sides.


can be carried out by two element energy meter, the connections of which are similar to the connections of two watt-meter for power measurement in the three phase three wire system.

→ These meters are classified as

(i) Three Element Energymeter.

(ii) Two Element Energymeter.

### Three Element Energymeter



→ This meter consists of three elements. The construction of an individual element is similar to that of a single phase energy meter.

→ The pressure coils are denoted as  $P_1, P_2$ , &  $P_3$  to the current coils are denoted as  $C_1, C_2$  &  $C_3$ .

→ All the elements are mounted in a vertical line in common case and have a common spindle, gearing and register mechanism.

→ The coils are connected in such a manner that the net torque produced is sum of the torque due to all the three elements. These are employed for three phase four wire system where fourth wire is a neutral wire.

→ The current coils are connected in series with the lines while pressure coils are connected across a line of a neutral.

→ Three phase element is always cheaper than three units of single phase energy meter.

→ But due to interaction b/w eddy currents produced by one element with the flux produced by another element, there may be errors in the measurement. Phase energy meter such errors can be removed by table adjustments.

## UNIT-3

### Instrument Transformer

#### Introduction:-

- For measurement of high current and high voltage's instrument Transformers are used.
- They can be used for irrespective of the voltage and current ratings of the ac circuits.
- These Transformers not only extend the range of the low range instruments but also isolate them from high currents to high voltages of ac circuits.
- Two types of instruments Transformers
  - a. Current transformers (C.T)
  - b. Potential transformers (P.T)

#### Ratios of instrument transformers :-

##### 1. Transformation Ratio [R] :-

It is also called as Actual ratio and is defined as the ratio of the magnitude of actual primary phasor to the corresponding magnitude of actual secondary phasor.

For C.T  $\times$  [at turns]

$$R = \frac{\text{magnitude of actual primary current}}{\text{magnitude of actual secondary voltage}}$$

##### 2. Nominal Ratio [kn] :-

The nominal ratio is defined as the ratio of rated

primary quantity to the rated secondary quantity either current or voltage for R.T.

for C.T

$$k_n = \frac{\text{Rated primary current}}{\text{Rated secondary current}}$$

For P.T

$$k_n = \frac{\text{Rated primary current}}{\text{Rated secondary current}}$$

3. Turns Ratio :-

$$\text{For C.T} \quad k_n = \frac{\text{No. of turns of secondary winding}}{\text{No. of turns of primary winding}}$$

$$\text{For P.T} \quad n = \frac{\text{No. of turns of primary winding}}{\text{No. of turns of secondary winding}}$$

4. Ratio Correction Factor (RCF) :-

It is the ratio of transformation ratio to ratio of D.R.

$$\boxed{RCF = \frac{R}{k_n}}$$

[R] actual resistance

5. Burden of an instrument Transformer :-

$$\text{Total Secondary Winding Burden} = [\text{Secondary winding currents}]^2 \times P.C.$$

Total impedance of secondary circuit incl. load other winding

It is convenient to express load across the secondary winding terminals as the output in V.A.

ampere at the noted secondary winding voltage.

### Current Transformers:-

The current transformer consists of primary windings and secondary windings. In this the primary winding consists of few no. of turns and secondary winding consists of large no. of turns. This is shown in figure and its equivalent circuit is shown in figure.





Fig. 2 Equivalent circuit of current transformer

Terms belongs to Current transformer :-

$V_1$  = Supply Voltage (or) transformer primary winding applied

$R_1$  = Resistance of primary winding.

$X_1$  = Reactance of primary winding.

$E_1$  = Primary induced Voltage

$N_1$  = No. of turns in primary winding.

$V_2$ ,  $R_2$ ,  $X_2$ ,  $E_2$ ,  $N_2$  are the corresponding values of secondary

$I_{ex}$  = magnetising Component of Existing Current

$I_w$  = working (or) Loss Component of existing current.

$\alpha$  = angle b/w existing current  $I_0$  and working flux

$\delta$  = Angle b/w secondary induced voltage and Secondary current

$\Delta$  = Angle b/w secondary terminal " " " "

$\theta$  = phase angle of transformer is angle b/w " "

The turns ratio of current transformer  $K = \frac{\text{No. of secondary winding turns}}{\text{No. of primary winding turns}}$

Consider the phasor diagram for current transformer


for inductive loads is shown in figure. 10 stepans.

- \*  $\phi$  is common for both Part A & B if it is taken as before.
- \* Due to secondary voltage drop  $[I_2(R_2 + jX_2)]$   $V_2$  lags

behind  $\epsilon_2$   $E_2 = V_2 + I_2 R_2 + I_2 \times z_2$  phasing

\* primary load current  $I_2'$  and Load Current  $I_2$  will be  $180^\circ$  out of phase.

$$^{10} \text{Of } I_1 = I_{21} + I_{30}$$



phasor diagram of a current transformer

Transformation Ratio (R) :-

multiple bins of three patterns with slope =  $\infty$


Consider a small section of the phasor diagram as shown in fig. we have

$\angle bac = 90^\circ - \delta - \alpha$  [By construction place dipole at side of  $\triangle abc$  at  $90^\circ$  to  $abc$  side. Now angle  $\delta + \alpha$  is reflex angle  $\Rightarrow \delta + \alpha = 180^\circ$  and  $\angle bac = 10^\circ$  here]

For right angle triangle  $abc$

$$\text{Since } (90 - \delta - \alpha) = \frac{bc}{ac}$$

$$\Rightarrow bc = 10 \sin(90 - \delta - \alpha) [\because ac = 10]$$



$$= 10 \sin[90 - (\delta + \alpha)]$$

$$\text{Opposite} = bc = 10 \cos(\delta + \alpha) \rightarrow ①$$

$$\text{Similarly } ab = 10 \cos(90 - \delta - \alpha) = 10 \sin(\delta + \alpha) \rightarrow ②$$

$$\text{Now } \Delta abc, ac^2 = ab^2 + bc^2$$

$$\text{Forming, we get } ac^2 = (ba + ab)^2 + bc^2$$

$$I_1^2 = [10 \sin(\delta + \alpha) + kI_2]^2 + 10^2 \cos^2(\delta + \alpha)$$

$$\text{Simplifying, we get } I_1^2 = 10^2 \sin^2(\delta + \alpha) + k^2 I_2^2 + 2kI_2 10 \sin(\delta + \alpha) + 10^2 \cos^2(\delta + \alpha)$$

$$\text{ratio } \frac{I_1^2}{I_2^2} = \frac{10^2 [\sin^2(\delta + \alpha) + \cos^2(\delta + \alpha)] + k^2 I_2^2 + 2kI_2 10 \sin(\delta + \alpha)}{I_2^2}$$

$$\text{From previous } I_1^2 = 10^2 + k^2 I_2^2 + 2kI_2 10 \sin(\delta + \alpha) \quad [\because \sin^2 + \cos^2 = 1]$$

Now in a well designed current transformer,  $k$  is very small.

So  $I_1^2$  is small. So simply replace  $I_1^2$  by  $I_1^2 \sin^2(\delta + \alpha)$

for our simplicity.

$$I_1^2 = I_1^2 \sin^2(\delta + \alpha) + k^2 I_2^2 + 2kI_2 10 \sin(\delta + \alpha)$$

$$\Rightarrow I_1^2 = (10 \sin(\delta + \alpha) + kI_2)^2$$

$$\Rightarrow I_1 = kI_2 + 10 \sin(\delta + \alpha)$$

The transformation (ratio of current transformer) is given as

$$R = \frac{I_1}{I_2} = \frac{kI_2 + 10 \sin(\delta + \alpha)}{I_2}$$

$$= k + \frac{10 \sin(\delta + \alpha)}{I_2} \rightarrow ③$$

Although only approximate Eq. 3 is sufficiently accurate for practically all purpose. The above theory is applicable to case when the secondary burden has a lagging power-factor i.e. when the burden is inductive which is normally the case.

For all cases Eq. (8) further expanded as (see ab), (see c)

$$R = k + \frac{50}{r^2} \left[ \sin \delta \cos \alpha + \cos \delta \sin \alpha \right]$$

for  $r = 3.0$  m  $\Rightarrow (r=3.0)$  m  $\Rightarrow R$

$$R = k + \frac{[a \sin(\delta - \pi) w \cos \delta]}{\pi_2}$$

$$\begin{aligned} \text{Here } \sin = \text{Ocosa} \\ \text{or } \text{Oc} = \text{Osina} \end{aligned}$$

phase angle ( $\theta$ ) :-

The phase angle  $\phi$  is also called as phase angle of transformer and it is defined as the angle b/w primary current and reversed secondary currents.

(b) This angle is generally taken off and used for the reverse.

( $\rightarrow$ ) Secondary current leads the primary current -ve for the reversed secondary current. ( $\rightarrow$ ) The primary current lags the secondary current.

∴ Here the angle between  $\vec{V}_2$  and  $\vec{V}_1$  is  $0^\circ$ . So phase angle of the transformer is  $0^\circ$ .

From phasor diagram  $\tan \theta = \frac{bc}{ab}$   $\Rightarrow \frac{bc}{ab} = \frac{I_2 \cos(\phi + \alpha)}{I_1 \sin(\phi)}$

As  $\theta$  is very small,  $\tan \theta \approx \theta$   $\Rightarrow$   $\theta = 7.8^\circ$

መመሪያ 29 የመተዳደሪያ ቅጂ, TOSCS (ዶ-፳) አስተማሚያ ተደርግ


$$K_1 \rightarrow 10 \sin(\delta + \alpha)$$

Now  $\delta_0$  is very small when compared to  $k_{12}$  so  $\delta_0$

$\sin(\omega t + \alpha)$  is neglected.

## Potential Transformers

Current transformer consists of primary & windings and secondary windings. In similarly potential transformers also consist primary and secondary windings. In the potential transformer primary winding consist long no. of turns, and secondary winding consist of new no. of turns. The potential transformer is shown in fig and its equivalent circuit is shown in fig.



## Equivalent circuit of potential transformer

Terms belongs to potential transformer :-

$V_1$  = primary voltage or supply voltage

$R_1$  = resistance of primary winding

$X_1$  = reactance "  $2002 \text{ m}^2 - 2203 \text{ m}^2$ "

$E_1$  = primary induced voltage

$N_1$  = NO. of turns in primary windings

$V_2, R_2, X_2, \& N_2$  are corresponding values of secondary

$I_0$  = exciting current

$I_M$  = magnetising component of exciting current

$I_W$  = working (or) loss component of exciting current

$\alpha$  = angle below to exciting current  $I_0$  and working

current in primary & primary flux

$\beta$  = angle below to secondary terminal voltage and

from terminals secondary currents (magnetizing winding)

to refer to terminals primary currents from input to output

$\theta$  = angle between primary & reversed secondary voltage.

$\theta$  = phase angle of transformer i.e. angle below primary and reversed secondary voltage.


The turns ratio of potential transformer

$$K = \frac{\text{no. of primary winding turns}}{\text{no. of secondary winding turns}}$$

Secondary voltage when referred to primary side

are to be multiplied by  $K$  when secondary currents are referred to primary side they must be divided by  $K$ .

Consider the phasor diagram for potential transformer for inductive loads is shown in fig. An enlarged concise phasor diagram of potential transformer is shown in figure directly to find its inductive



From Fig  $\cos\theta = \frac{OA}{OB} \Rightarrow OA = N_1 \cos\theta \rightarrow ①$

From Fig OA can be written as

$$OA = KV_2 + K I_2 R_2 \cos\Delta + K I_2 X_2 \sin\Delta + I_1 R_1 \cos\beta + I_1 X_1 \sin\beta \quad ②$$


phase angle is very small i.e.  $\theta \ll 1$   $\cos\theta \approx 1$  and therefore both V1 and reversed V2 can be taken perpendicular to  $\phi$  and it is shown in fig

From fig  $\angle OC\alpha \approx \beta, \angle OCG \approx \Delta$

From this  $I_1 \cos\beta = CG + GD$

$$I_1 \cos\beta = \frac{I_2}{K} \cos\Delta + I_{10}$$

$\Delta \cos\beta = I_1 \sin\beta = I_1 + \frac{I_2}{K} \sin\Delta$



Substituting the above values in Eq ② we get

$$V_1 = KV_2 + KI_2 \left( R_2 \cos \Delta + V_2 \sin \Delta \right) + R_1 \left( I_{10} + \frac{I_2}{K} \cos \Delta \right) + \left( I_{11} + \frac{I_2}{K} \sin \Delta \right) X_1$$

$$= KV_2 + KI_2 R_2 \cos \Delta + KI_2 X_2 \sin \Delta + R_1 I_{10} + \frac{I_2 R_1}{K} \cos \Delta + I_{11} X_1 + \frac{I_2 X_1}{K} \sin \Delta$$

$$= KV_2 + \frac{I_2}{K} \cos \Delta \left( KR_2 + R_1 \right) + I_2 \sin \Delta \left( KX_2 + \frac{X_1}{K} \right) + I_{10} R_1 + I_{11} X_1 \rightarrow ③$$

$$= KV_2 + \frac{I_2}{K} \cos \Delta R_{1e} + \frac{I_2}{K} \left( K^2 R_2 + R_1 \right) + \frac{I_2}{K} \sin \Delta \\ \text{referring to the primary side}$$

$$V_1 = KV_2 + \frac{I_2}{K} \cos \Delta R_{1e} + \frac{I_2}{K} \sin \Delta X_{1e} + I_{10} R_1 + I_{11} X_1$$

$$V_1 = KV_2 + \frac{I_2}{K} [R_{1e} \cos \Delta + X_{1e} \sin \Delta] + I_{10} R_1 + I_{11} X_1$$

Here  $R_{1e}$  = Equivalent resistance of the transformer  
refered to the primary side.

$X_{1e}$  = Equivalent reactance of the transformer  
refered to the primary side.

$\therefore$  Actual transformation ratio,  $R = \frac{V_p}{V_s} = \frac{V_1}{V_2}$

$$\therefore R = KV_2 + \frac{I_2}{K} [R_{1e} \cos \Delta + X_{1e} \sin \Delta] + I_{10} R_1 + I_{11} X_1$$

$$R = K + \frac{I_2}{K} \left[ R_{1e} \cos \Delta + X_{1e} \sin \Delta \right] + I_{10} R_1 + I_{11} X_1$$

Eqn ③ also be written as  $R = K + \frac{V_2}{I_2}$

$$V_1 = KV_2 + I_2 \cos \Delta k_i \left[ R_2 + \frac{R_1}{K^2} \right] + I_2 \sin \Delta k_i \left[ X_2 + \frac{X_1}{K^2} \right] + I_w R_1 + I_u X_1$$

$$-KV_2 \approx [KV_2 + KI_2 \cos \Delta R_{2e}] + KI_2 \sin \Delta X_{2e} + I_w R_1 + I_u X_1$$

$$V_1 = KV_2 + KI_2 [\cos \Delta R_{2e} + \sin \Delta X_{2e}] + I_w R_1 + I_u X_1$$

Here  $R_{2e}$  = Equivalent resistance of the transformer referred to secondary side.

$X_{2e}$  = Equivalent reactance of the transformer referred to secondary side.

∴ Actual transformation ratio  $R = \frac{V_1}{V_2}$

$$\boxed{R = K + \frac{KI_2 [\cos \Delta R_{2e} + X_{2e} \sin \Delta] + I_w R_1 + I_u X_1}{V_2}}$$

Phase angle ( $\theta$ ):

The phase angle  $\theta$  is also called as phase angle of transformer and it is defined as the angle b/w primary voltage and reversed secondary voltage.

From phasor diagram  $\tan \theta = \frac{ab}{ba}$

$$ab = I_1 X_1 \cos \beta - I_1 R_1 \sin \beta + K I_2 X_2 \cos \Delta - K I_2 R_2 \sin \Delta$$

$$ba = I_1 X_1 \cos \beta - I_1 R_1 \sin \beta + K I_2 X_2 \cos \Delta - K I_2 R_2 \sin \Delta$$

$$KV_2 + KI_2 R_2 \cos \Delta + KI_2 X_2 \sin \Delta + I_1 R_1 \cos \beta + I_1 X_1 \sin \beta$$

The terms in denominator involving  $I_1$  and  $I_2$  are small so they are neglected as compared with  $KV_2$ .

$$\tan\theta = \frac{I_1 X_1 \cos\beta - I_1 R_1 \sin\beta + k I_2 X_2 \cos\alpha - k I_2 R_2 \sin\alpha}{k V_2}$$

$$= \frac{X_1 [I_w + \frac{I_2}{R} \cos\alpha] - R_1 [I_u + \frac{I_2}{R} \sin\alpha] + k I_2 X_2 \cos\alpha}{k V_2}$$

$$= \frac{k I_2 R_2 \sin\alpha}{k V_2}$$

$$= \frac{I_2 \cos\alpha (X_1 - \frac{k X_2}{R}) - I_2 \sin\alpha (\frac{R_1}{R} + k R_2) + I_w X_1 - I_u R_1}{k V_2}$$

$$\tan\theta = \frac{I_2 \cos\alpha (X_1 - \frac{k X_2}{R}) - I_2 \sin\alpha (\frac{R_1}{R} + k R_2) + I_w X_1 - I_u R_1}{k V_2}$$

$$\tan\theta = \frac{I_2 \cos\alpha (X_1 - \frac{k X_2}{R}) - I_2 \sin\alpha (\frac{R_1}{R} + k R_2) + I_w X_1 - I_u R_1}{k V_2}$$

$$\tan\theta = \frac{I_2 \cos\alpha X_1 - \frac{I_2}{R} \sin\alpha R_1 + I_w X_1 - I_u R_1}{k V_2}$$

$$\tan\theta = \frac{I_2}{k} \left[ X_1 \cos\alpha - R_1 \sin\alpha \right] + I_w X_1 - I_u R_1$$

$$\text{For small } \theta \text{ values, } \tan\theta = 0.203 \times 1 = 0.203$$

$$\text{Phase angle } \theta = \frac{0.203}{k} \left[ X_1 \cos\alpha - R_1 \sin\alpha \right] + I_w X_1 - I_u R_1$$

$$= 0.203 \times 1 + 0.203 \times 1 + 0.203 \times 1 = 0.609$$

Similarly we get  $\theta$  value in resistance and reactance with deflected secondary.

$$\Theta = \frac{I_2}{V_1} (x_2 e \cos \Delta + R_2 e \sin \Delta) + \frac{I_2 \omega x_1 - I_1 R_1}{V_1 S}$$

Sadie  
-ns

The  $\Theta$  values in degrees just multiplied by  $(\frac{180}{\pi})$

Tower Factor meter -  $\sqrt{\text{power factor}}$  ①

The power in single phase A is circuit  $P_s$  given by  $P = V I \cos \phi$

→ By using precise Voltmeter, Ammeter and Wattmeter in the circuit, the readings of  $V$ ,  $I$  and  $P$  can be obtained then power factor can be calculated as

$$\text{Cos}\phi = \frac{P}{VI}$$

→ But this method is not accurate. The errors in all the meters together cause the error in power-factor.

Calculation. The meter which indicates the instantaneous power-factor of the circuit is called power-factor meter.

Basic construction of power-factor meter is similar to a wattmeter. It has two circuits.

① The current circuit carries current or fraction of current in the circuit whose power-factor is to be measured.

② The voltage circuit in which Voltage coil is split into two parallel paths, one inductive and one non-inductive. The currents in the two paths are proportional to the voltage of the circuit.

→ Thus the deflection depends upon the phase difference between the main current through current circuit, the currents in the two branches of the circuit.


(Q8) What are two types of power factor meters?

① Electrodynamometers' type

② moving iron type

Single phase Electrodynamometer type power factor meter:

→ The construction of electrodynamometer type power factor meter is similar to the construction of electrodynamometer type.



→ The F<sub>1</sub> - F<sub>2</sub> are two fixed coils which are connected in series.

→ The A-B are the two moving coils which are connected to each other. So that their axes are at 90° to each other. They move together carrying the pointer.

which indicates the power factor of the circuit.

→ The fixed coils  $F_1$ - $F_2$  carry the main current in the circuit. The fraction of other current is passed through the fixed coils. Thus the magnetic field produced by the fixed coils is proportional to the main current.

→ The moving coils A-B are identical and are connected in parallel across the supply voltage and hence called pressure coil or voltage coil. The currents through the coils A to B are proportional to the supply voltage.

→ The coil A has a non-inductive resistance  $R$  in series with it while the coil B has an inductance  $L$  in series with it.

→ The values of  $R$  and  $L$  are so adjusted that the coils A and B carry equal currents at normal frequency so that normal frequency  $\omega = \frac{R}{L}$ .


→ The current through coil A is in phase with the supply voltage while the current through coil B lags the supply voltage by nearly  $90^\circ$  due to highly inductive nature of the circuit.

→ Due to 'L' current through coil B is frequency dependent while current through coil A is frequency independent.

→ The current in the coils A and B are equal and produce the magnetic fields of equal strength.

which have a phase difference of  $90^\circ$  between them. The coils are also mutually perpendicular to each other.

→ The controlling torque is absent. The contacts to the moving coils are made with the help of extremely fine ligaments which give no controlling effect on the moving coil.



→ Consider the position of the moving system as shown in fig.

→ Assume that the current through Coil "B" lags voltage exactly by  $90^\circ$  and also assume that the field produced by the fixed coils is uniform & in the direction X-X as shown in fig.

→ Due to the interaction of the fields produced by the current through various coils, both coils A & B experience a torque.

→ The windings are arranged in such a manner that the torques experienced by coil A and B are opposite to each other. Hence the pointer attains an equilibrium position when these two torques are equal.

→ The torque on each coil, for a given coil current will be maximum when the coil is parallel to the field produced by  $F_1 - F_2$  i.e. deflection  $X-X$ .

→ Let  $\phi$  = power factor angle  $\theta = \phi$   
 $\theta$  = Angle of deflection

→ "θ" is measured from the vertical axis in the equilibrium position. Similar to a dynamometer type wattmeter, torque on coil "A" is given by

$$T_A = KV^2 \cos \phi \cos(90^\circ - \theta) \quad k = \text{constant}$$

→ The current through coil A is in phase with system voltage  $V$  and it moves in a magnetic field which is proportional constant for radial field is not constant for parallel field & is proportional to  $\cos(90^\circ - \theta)$ .

Similarly current in coil "B" lags the supply voltage by  $90^\circ$  & it moves in same field. Hence the torque on B is proportional to  $\cos(90^\circ - \phi)$  i.e.  $\sin \phi$  and  $\cos \theta$ .

$$T_B = KV^2 \sin \phi \cos \theta$$

$$\text{In equilibrium position } T_A = T_B$$

$$\cos \phi \cos(90^\circ - \theta) = \sin \phi \cos \theta$$

$$\cos \phi \sin \theta = \sin \phi \cos \theta$$

$$\sin \theta = \frac{\sin \phi}{\cos \phi} \cos \theta$$

$$\tan \phi \cos \theta = \tan \theta$$

Sine  
case

$\tan \phi = \frac{\text{opposite}}{\text{adjacent}}$  or  $\tan \phi = \frac{\text{load voltage}}{\text{load current}}$  or  $\tan \phi = \frac{V_L}{I_L}$

$$\theta = \phi$$


base angle  $\theta = \phi$

angle  $\theta$  to  $\alpha = \phi$

Thus the angular position taken up by the moving coils is equal to the system power factor angle. The scale of the instrument can then be calibrated in terms of power factor values.

The operation of the instrument is dependent on the specific supply frequency.

Three phase Electrodynamometer power factor meter:



→ Fig shows the construction and connections of 3 phase Electrodynamometer type power factor met.

→ This meter is only useful for balanced loads.

- The two moving coils are so placed that the angle b/w their planes is  $120^\circ$ .
- They are connected across two different phases of the supply circuit.
- Each coil has a series resistance.
- There is no necessity for phase splitting by artificial means.
- Since the required phase displacement b/w current  $I_A$  and  $I_B$  in the two moving coils can be obtained from the supply itself as shown:

Voltage applied across coil A is  $V_{12}$  and as the its circuit is resistive, current  $I_A$  is in phase with  $V_{12}$ .  
 Voltage applied across coil B is  $V_{13}$  and current is in phase with  $V_{13}$  as the circuit of coil B is resistive.

Let  $\phi$  = phase angle of the circuit  
 and of coil  $\theta$  = angular deflection from the plane of difference

$$V_1 = V_2 = V_3 = V$$

Torque acting on coil A is:

$$T_A = K_{12} I_{\max} \cos (\beta (30^\circ + \theta) \sin (60^\circ + \theta))$$

$$= \sqrt{3} K V \cdot I_{\max} \cos (30^\circ + \theta) \sin (60^\circ + \theta)$$

Torque acting on coil B is given by

$$T_B = KV_{13} I_{max} \cos(30^\circ - \theta) \sin(120^\circ + \theta)$$

$$= \sqrt{3} KV_1 I_{max} \cos(30^\circ - \theta) \sin(120^\circ + \theta)$$

Torques  $T_A$  and  $T_B$  act in the opposite directions of rotation. moving system takes up a position where  $T_A = T_B$

$$\therefore \cos(30^\circ - \theta) \sin(60^\circ + \theta)$$

$$\cos(30^\circ - \theta) \sin(120^\circ + \theta)$$

Solving the above exp, we have  $\theta = \phi$

Thus angular deflection is equal to the phase angle of the AC circuit which is the meter is connected.

The 3-phase power factor gives indications which are independent of wave-form of freq of supply, since the currents in the two moving coils have equally effects by any change of frequency.

For measurement of power factor in 3-phase Unbalance system a two element power factor meter has to be used.

Moving iron power factor meter:

The advantages of moving iron power factor meter are:

Over the dynamometer type are.

What are the working forces in moving iron ore layer.

2. All coils in moving iron are fixed so no ligaments are required.
  3. A scale extends over  $360^\circ$ .

But due to the losses in the iron parts the accuracy

of moving iron power factor meter is much less than

**Electrodynamometer type:** Two types of moving iron pf meter.

According to whether the operation of the instrument depends upon a rotating field (or) no. of alternating fields; where  $n = 2$  or  $3$  etc.


**Rotating-field type**

- ## 2. Alternating field type.

Rotating field type moving from power factor meter :-

→ These are 3 fixed  $F_1, F_2$  &  $F_3$  whose axes are displaced from each other by  $120^\circ$ .

→ The coils are supplied from a three phase supply through current transformer.



→ The coil  $F_1$  is supplied from phase  $R_1 R_2$ , from  $F_3$  from  $S$ . ~~but no armature or elios. NA~~

→ The coil  $\Phi$  is placed at the centre of the three fixed coils and is connected across any two lines, the supply through a series resistance.

→ Inside coil  $\Phi$ , there is a short pivoted iron core pivoted to wrap out ~~outwards~~ <sup>upwards</sup> ~~upwards~~ <sup>upwards</sup> The rod carries two sector shaped vanes ~~upwards~~ <sup>upwards</sup> at its ends.

→ The same rod carries damping vane of a point, the control springs absent.

→ The coil  $\Phi$  and the iron system produces an alternating flux with interact with the flux produced by the fixed coils  $F_1, F_2$  and  $F_3$ .

→ Due to resistance of ~~in~~ <sup>in</sup> the current in coil  $\Phi$  is in phase with the supply voltage.

→ So the deflection of the moving system is approximately equal to the power factor angle of the three phase circuit.

→ The flux produced by the coils  $F_1, F_2$  &  $F_3$  is rotating magnetic flux which creates an induction motor action.

→ It tries to keep moving system continuous rotating.

- But it sets moving system in a definite position due to use of high resistivity iron parts. Such high resistive parts deduce the induced currents and stops their continuous rotation.
- The meter can be used for balanced load. It is also called westing house power factor meter.
- It is calibrated at the normal supply frequency and on cause serious error is used at any other frequency.


### Alternating field type moving iron power factor meter

- This instrument consists of three moving iron and vanes, which are fixed to the common spindle. Spindle carries damping vanes and the pointer.
- The moving iron vanes are sector shaped similar to those used in the rotating field type meter.
- The blades of these sectors have an angle  $120^\circ$  with respect to each other.

→ These iron sectors are separated from each other by the spindle by the non-magnetic spacers denoted as S.

- The  $Q_1$ ,  $Q_2$  &  $Q_3$  are the iron sectors. These iron sectors are magnetized by the coils  $S_1$ ,  $P_2$  &  $P_3$ .

These are voltage coils.   
 → These coils are connected across the three phases, thus the current through them are proportional to the phase voltage of the three phase system.



Alternating field type

→ The current coil is divided into two equal parts P1 and P2 which are parallel to each other. The current coil carries one of the three line currents.

→ One part  $F_1$  of the current coil is on one side of the moving system and other  $F_2$

the other side.

- when connected in the circuit coil is [on one side of the moving system and other  $F_2$  on the other side]
- when moving system moves attains such a position in which mean torque on one of the iron pieces gets neutralized by the torque produced by the other two iron pieces.
- In this position, the deflection of the pointer is equal to phase angle b/w the current and voltages of the three phase system.
- The instrument is used for the balanced loads but can be modified for unbalanced loads. The voltage coils are at different levels hence the resultant flux is not rotating but alternating.
- This instrument is also called a power factor meter.

## UNIT - IV

### Potentiometer

Introduction:

- A Potentiometer is an instrument designed to measure an unknown voltage by comparing it with a known voltage. The known voltage may be supplied by a standard cell or any other known voltage reference source.
- Advantage of the potentiometer is that it makes use of a balance or null condition no current flows and hence no power is consumed in the circuit.
- Potentiometer is extensively used for calibrations of voltmeters and ammeters and has in fact become the standard for the calibration of these instruments.
- Since a potentiometer measures voltage, it can also be used to determine currents simply by measuring the voltage drop produced by the unknown current passing through a known standard resistance.
- Potentiometers are of two types:
  - \* DC potentiometer, not only measure the unknown emf but also currents and resistance can be measured. Also ammeter and voltmeter and wattmeter can be calibrated.
  - \* AC potentiometer finds application in the measurement of unknown emf, power supplied to a load, and self-inductance of a coil.

## Principle of potentiometer

Statement

The potentiometer works on the principle of opposing unknown E.m.f by a known E.m.f with the negative terminals of both the E.m.f connected together, while the positive terminals connected together through galvanometer as shown in figure.

When the E.m.f's are of same ratio then there is no deflection in galvanometer as shown in figure.

When the E.m.f's are of same ratio then there is no deflection in galvanometer as shown in figure.

values, there is no deflection in galvanometer. Thus to measure the unknown E.m.f by using the above method, the known E.m.f used must be rotamitable be variable. Another representation of method is shown in fig:-

Important requirement is balancing E.m.f's. Note that known E.m.f should be varied to give larger or known values but it is practically very difficult.

Hence alternatively if the known E.m.f is connected in parallel with and in opposition to a voltage drop measured across the resistor is shown in fig below.





Fig:- Alternative method of balancing E.m.f

The main advantage of this method is that the current in the resistor can be varied easily to obtain any desired voltage with very fine adjustment. The voltage drop across resistor can be determined by calibrating the resistor with standard cell.

Basic Potentiometer circuit (or) slide wire potentiometer:-


→ The principle of operation of all potentiometer is based on the circuit shown below, which is also basic slide wire potentiometer.



- 1) With switch "S" in the operating position and galvanometer "K" open the battery supplies the working current through rheostat "R" of the slide wire.
- 2) The working current in slide wire may be varied by changing the rheostat setting.
- 3) The method of measuring the unknown voltage "E" depends on finding a position for the sliding contact.


- 4) When the galvanometer is closed, and the sliding contact is moved along the slide wire, until the galvanometer shows zero deflection.
- 5) Then the unknown Voltage "E" is equal to the voltage  $E_1$  across portion of ac of slide wire.
- 6) The slide wire has a uniform cross-section and hence uniform resistance along its entire length.
- 7) A calibrated scale is placed along the slide wire so the sliding contact can be placed accurately at any desired position along the slide wire.
- 8) Since the resistance of slide wires is known accurately the voltage drop along the slide wire can be controlled by adjusting the value of working current.
- 9) The process of adjusting the working current so as to make the voltage drop across a portion of sliding wire against a standard reference source is known as standardisation.

Procedure for Standardisation



→ The procedure for standardisation is shown by the above fig.

- Here the  $B_1$  is a battery with a ample capacity and 'R' is a regulating resistance.
- $B_2$  is a standard Cell - usually it is Weston Standard cell with EMF of 1.0186 Volts and  $R'$  is series resistance.
- $G_1$  is a sensitive galvanometer.
- The key "k" is closed and with the series resistance  $R'$  fully cut in, the sliding contact "c" is set against the division measured marked as 1.0186 Volts on the scale.
- A deflection is obtained in the galvanometer. This is brought down to near zero by operating the regulating resistance R.
- The series Resistance  $R'$  is fully cut out so as to increase the sensitiveness of the galvanometer.
- perfect balance i.e zero galvanometer deflection is obtained by properly adjusting  $R$  to meet position A.
- The potentiometer is now standardised and its direct reading on the standardised the regulating resistance "R" should be left undistributed at about zero, continue with a long period now to standardise it.
- stable now, so doing the same for the other part to about zero and so show stable zero.
- stable now, so doing the same for the other part to about zero and so show stable zero.
- stable now, so doing the same for the other part to about zero and so show stable zero.



→ A practical form of dc potentiometer which is very widely used is the Crompton potentiometer.

→ The potentiometer consists of a short slide wire AB of uniform cross section in series with a no. of resistance coils (15). The resistance of each coil being equal to the resistance of the slide wire.

→ There are two sliding contacts  $P_1$  and  $P_2$ ,  $P_1$  can slide over the slide wire and  $P_2$  can move over the studs of resistance coils.

→ The regulating resistance in the form of two variable resistor  $R_1$  and  $R_2$  joined in series.

- $R_1$  taking the form of a no. of coils of  $R_2$  taking the form of a slide wire.
  - There is a battery  $B$  of the ample capacity which supplies the slide wire current.
  - There is a change-over or multiple circuit switch  $S$  with 6 terminals. A standard Weston cell is connected across terminals marked as  $sc$  [standardisation circuit].
  - The battery whose E.m.f. is to be measured is connected across terminals 1, 1' (or) 2, 2' with due regard to polarity.
  - "G" is a sensitive galvanometer which is connected to the switch and the sliding contacts  $p_1$  and  $p_2$  through a key "K" as shown.
  - To unbalance current initially a resistance  $R_s$  is connected in series with the galvanometer.
- Operation:
- The potentiometer is standardised as the change-over switch is thrown to terminals  $sc, sc$  across which the standard cell is connected.
  - The sliding contact  $p_2$  is set at 10 and  $p_1$  is set at 0.0186 reading. The key "K" is closed and null deflection is obtained by adjusting resistances  $R_1$  and  $R_2$ .
  - The potentiometer is now standardised and it is direct reading. Resistors  $R_1$  and  $R_2$  are left undisturbed thereafter.
  - The change-over switch is moved to 1, 1' position, if the battery whose E.m.f. is to be measured is connected across

1.1. The potentiometer is again balanced i.e. null deflection is obtained by adjusting the positions of  $P_1$  and  $P_2$ .

→ The unknown e.m.f. is directly read off from the scale.


Example:

If  $P_2$  is at 1.2 and  $P_1$  is at 0.07, the measured value of the e.m.f. is 1.27 Volts.

Application of d.c. potentiometer see in between

1. Calibration of Ammeter:

An Ammeter can be calibrated by using d.c. potentiometer.



To (calibrate) calibration terminals of d.c. potentiometer → meter.

$R_s \rightarrow$  Standard Resistance  
 $A \rightarrow$  Ammeter to be calibrated.

The ammeter to be calibrated is connected in series with a standard resistance of  $R_s$  of a variable load. Supply is obtained from a suitable d.c. source. A small current is passed through the load which develops a voltage across  $R_s$  is applied to a V.R. box. The o/p voltage of the V.R. box is measured in the usual way using d.c. potentiometer. The ammeter is noted of repeated for different currents.

$$\text{Actual current (A)} = \frac{\text{Potentiometer Reading}}{R_s \times \text{standard Resis}}$$

percentage error is calculated for each ammeter reading

as अपनी जीवनी की विभिन्न घटनाएँ Sindi-Gant द्वारा लिखी गई हैं।

Find a suitable binode to calibrate the DSC cell and obtain its calibration

Voltmeter can be calibrated using d.c potentiometer

The necessary setup is shown in fig.

Any desired voltage within the range of the voltmeter to be calibrated can be obtained by using the potential divider shown in fig. This circuit diagram shows a DC supply source connected to a variable resistor (potentiometer) and a voltmeter. The output voltage across the potentiometer is measured by the voltmeter. A 'V' symbol indicates the voltmeter connection. The circuit is labeled 'To Calibration terminal' and 'Ratio Box'. The text also notes that the output voltage is half of the input voltage.

Voltage is applied to the input terminals of a <sup>VR box</sup> (10) volt-ratio box. The voltmeter to be calibrated is connected across these terminals. The op voltage of VR box is measured accurately with a.d.c potentiometer.

The reading of the voltmeter is noted. This is the indicated voltage,  $V_{ind}$ .

The test is repeated for several different voltages

$$\text{Actual Voltage, } V_{\text{act}} = \frac{\text{Potentiometer reading}}{10}$$

$$\text{1. Error} = \frac{\text{Vind} - \text{Vaart}}{\text{Vind}} \times 100$$

The calibration curve is obtained by plotting % error against indicated voltage.

biode asproton over self, referentievolg en van op ←  
referentievolg self standa de was de schrijver ni beïnvloed sei

## Measurement of Resistance

The unknown resistance  $R$  is connected in series with a standard resistance  $S$ , an ammeter of suitable range and variable load supply for the circuit is obtained from a suitable d.c. source. Different currents are passed through  $R$  and  $S$  for each current, the voltages developing across  $R$  and  $S$  are accurately measured with a d.c. potentiometer. Since the same current flows through both  $R$  &  $S$  we have:

$$\text{Voltage drop across } R = IR \text{ Volts}$$


$$\text{Voltage drop across } S = IS \text{ Volts}$$

$$\frac{IR}{IS} = \frac{\text{Voltage drop across } R}{\text{Voltage drop across } S} = \frac{R}{S}$$

(Or)  $R = S$  for Potentiometer Reading with  $R$ ,

Potentiometer reading with  $S$

ratio is the same during both measurements. knowing this ratio and the two potentiometer readings, the unknown resistance  $R$  can be computed.



R - unk  
con re  
stors  
S - star  
ard %  
star

### AC potentiometer

→ In an AC potentiometer, the two voltages should be balanced in magnitude as well as phase. A.C. potentiometer

are classified on the basis of method of measurement of unknown voltages. O.O is opposed to slaving and self.

ob other are two types of a.c. potentiometers.

(i) polar type a.c. potentiometer:-  
In which the magnitude and phase angle of unknown voltage are measured on different scales directly. The phase angle is measured with respect to some reference phase. As the voltage measured is represented in polar form as  $V \angle \theta$ ; the a.c. potentiometer is called polar type a.c. potentiometer.

(ii) co-ordinate type of a.c. potentiometer:-

In which the two components of an unknown voltage are measured on two different scales. One of the components measured is inphase component while remaining is quadrature component. Both the components are  $90^\circ$  out of phase each other. If  $V_A$  &  $V_B$  are inphase and quadrature component then the magnitude & phase angle of an unknown voltage can be represented as given by,

$$V = \sqrt{V_A^2 + V_B^2} \text{ and}$$

$$\theta = \tan^{-1} \left( \frac{V_B}{V_A} \right)$$

As the two components of the unknown voltage represent rectangular form of voltage, the potentiometer is called co-ordinate type a.c. potentiometer.